### *MEMORANDUM* City Hall Project

Date:

January 17, 2003

To:

Honorable Mayor and City Council

Through: Topy Wilson, City Manager

Greg Armendariz, City Hall Project Manager

Subject: Attachment to Council Agenda Item RA5: City Hall Progress Report

### **Contract Close Out Progress**

Two construction contractors (BBI Engineering & Sasco,) have completed all of their contract work, including all punchlist items. The work has been inspected and approved by staff. Staff recommends adoption of a resolution granting initial acceptance for each of these contracts, subject to a 1-year warranty on the work. There are six remaining contractors who are still working on punchlist items. These contractors are waiting on delivery of replacement parts, and are expected to complete their punchlist work over the next two months.

### **Contract Change Orders**

Nineteen contract change orders for various items of work, are recommended for approval. The largest change order is to add back (or rescind) a previously approved credit change order with Division II for an amount of \$151,222. When the City took over the project management, staff learned that this contractor had previously been overpaid by \$151,222. A credit (deductive) change order was processed for this amount. The original contract was appropriate for the full term of the contract, however, it was being spent a faster rate than anticipated due to the overcharging. The contractor also agreed to deduct the overpayment amount from subsequent invoices. Staff tracked all of the contractor's expenses, throughout the remaining duration of the contract and established that the total actual value of the labor and materials furnished by this contractor was for the actual original amount. The add back of \$151,222 is therefore recommended.

The other change orders represent additional work requested from several contractors, and credits to the City, due to trade damage, deleted work and other charges to contractors. The total amount for these 19 change orders is \$174,281. A change order summary sheet providing a description of the work for each change order is attached.

### **Cost Recovery**

Additional cost recoveries are being realized as the City closes out the multiple prime contracts. Staff is reconciling all of the contracts and purchase orders. Upon taking over the project, staff was in a better position to directly control costs (i.e. blueprinting, tracking backcharges and tracking actual contractor time and materials, to assure efficiencies from contractors are also passed on to the City, and utilizing consultants and other services on an as needed basis only.) The attached memo to Finance summarizes the total cost recoveries and savings for the

construction contracts, consultant and other services. The total amount is \$354,515.57, which will be added to the project contingency.

### **Budget**

...

The project contingency balance is \$494,113, after approval of the change orders recommended above and inclusion of the cost recoveries from the various contractors, vendors and consultants listed in the attached memo to Finance. Staff will make a budget status presentation at the Council meeting on January 21, 2003.

### MEMORAÑDUM City Hall Project

Date:

January 17, 2003

To:

Emma Karlan, Finance Director; Lou Zenzen, Purchasing Agent

From:/

Greg Armendariz, City Hall Project Manager

Subject: Request to Close Contract Purchase Orders

This memo is to request closure of the purchase orders for the construction contracts, vendors and consultants listed in the following tables. The remaining fund balances represent cost recovery and savings from each of these contracts. We have reviewed and reached agreement on the final cost recovery/cost savings with your purchasing and accounting staff. These remaining funds should be transferred back to the City Hall Project contingency.

The first table below lists the construction contracts, which have been accepted by Council and Project staff has reconciled all monetary issues with the Contractors.

	=,	Co	nstructio	n Contract	ors	
Contractors	Initia amo	l contract unt	Total ch order a	•	Final Contract	Funds in P.O. Cost Recovery /Savings
A & B Painting West	\$	195,671	\$	131,431	\$327,102	\$4,931.20
Allied Fire Protection	\$	283,000	\$	24,842	\$307,842	\$1,158.10
Clean Innovation	\$	29,275	\$		\$29,275	\$6,875.00
Cookson Rolling Doors	\$	36,762	\$	3,670	\$40,432	\$5,000.00
Ferma Corp.	\$	722,500	\$	160,048	\$882,548	\$3,000.00
Fetzer's	\$	1,63 <u>4,</u> 389	\$	(444,394)	\$1,189,995	\$16,086.60
JJR Construction (site concrete)	\$	897,000	\$	389,989	\$1,286,989	\$15,000.00
Mauck Sheet Metal	\$	107,015	\$\$	-	\$107,015	\$18,469.29
Metal Air Ironworks	\$	1,596,000	\$	(367,274)	\$1,228,726	\$31,392.00
R.L. Hellwig Mechanical	\$	639,619	\$	186,259	\$825,878	\$1,366.00
Rollie French (drywall)	\$	1,726,000	\$	926,990	\$2,652,990	\$93,248.00

Total cost savings =

\$196,526.19

In addition, the following table summarizes the purchase orders for vendors and consultants which should also be closed.

		Vendors & Consu	Itants	
Vendor or Consultant	P.O. #	Initial Contract Amount	Final Contract Amount	Cost Savings
ATC Associates	C902632	\$ 4,950	\$ 4,950	\$4,950
Environmental Health Consultants	C902627	\$50,000	\$50,000	\$44,000
Kim Parker & Assoc.	C902633	\$ 4,950	\$ 4,950	\$22,449.97
Great Mall of the Bay A	C902648	\$654,573.23	\$864,766	\$14,298
Moisture Control Technologies	C802697	\$30,000	\$30,000	\$16,302.37
Nolte & Associates	MA 0054	\$4,990	\$4,990	\$3,737.04
Sandis Humber Jones	MA 00051	\$40,000	\$164,000	\$17,252
San Jose Blueprint	\$90,000	\$90,000	\$90,000	\$35,000
		Tot	tal Cost Savings =	\$157,989.38

59069 R

City of Milpitas
455 East Calaveras Boulevard
Milpitas, CA 95035
Attention: Office of the City Clerk

Record without fee under Section 6103 - Government Code State of California

RESOLUTION NO. \_\_\_\_\_

# A RESOLUTION OF THE CITY COUNCIL OF THE CITY OF MILPITAS APPROVING INITIAL ACCEPTANCE OF MILPITAS CITY HALL PROJECT PROJECT NO. 8026

WHEREAS, the City of Milpitas has heretofore entered into a Contract with BBI Engineering, Inc., for the Audio, Visual and Teleconferencing Equipment & Installation for Milpitas City Hall, and the City Hall Project Manager of the City of Milpitas has recommended acceptance of said improvement as completed in accordance with plans, specifications and approved change orders and correction lists, and in accordance with the final inspection of said City Hall Project Manager.

NOW, THEREFORE, BE IT RESOLVED that the City Council of the City of Milpitas does hereby accept said improvement as completed on this 21 day of January, and does hereby authorize and direct the City Hall Project Manger \_\_\_\_ of the City of Milpitas to file a Notice of Completion in accordance with the provisions of Section 3093 of the Civil Code of the State of California, and does hereby authorize and direct the City Hall Project Manager to file a Certificate of Completion in accordance with the provisions of Section 4005 of the Government Code of the State of California, if said work was by day's labor or force account. The penal sum of the faithful performance bond securing said improvement may be reduced to the sum of \$1,153.064.00 upon request of principal and surety, said penal sum as reduced to apply from the date of completion and acceptance of said improvements and to extend for the balance of the term of said bond, provided that said term shall not be less than one year.

	PASSED AND ADOPTED this	_ day of	, 20, by the following vote:
	AYES:		
	NOES:		
	ABSENT:		
	ABSTAIN:		
ATTE	ST:	,	APPROVED:
G 11 B			Tara C. Estavas Mayor
Gail B	lalock, City Clerk		Jose S. Esteves, Mayor
APPRO	OVED AS TO FORM:		
Steven	T. Mattas, City Attorney		

-1-

Resolution No.

City of Milpitas 455 East Calaveras Boulevard Milpitas, CA 95035 Attention: City Engineer

Record without fee under Section 6103 - Government Code State of California

### CITY OF MILPITAS

### NOTICE OF COMPLETION

(Civil Code Section 3093)

### NOTICE IS HEREBY GIVEN:

- 1. On or about August 7, 2001, City of Milpitas, a municipal corporation of the State of California, whose address is City Hall, 455 East Calaveras Boulevard, Milpitas, California, 95035 (as owner) entered into a contract for work of improvement, to wit:
- 2. A description of the site of which the City is owner for said work of improvement is City of Milpitas, Santa Clara County, California, more particularly described as: City Hall Project, Project No. 8026
- 3. The nature and interest or estate of the City as owner of said site is in fee: Milpitas City Hall
- The name and address of the original contractor is: BBI Engineering, Inc., 241 Quint Street, San Francisco, CA 94124
- 5. A general statement of the kind of work done or materials furnished to the City is as follows:

  Audio, Visual and Teleconferencing Equipment & Installation for Milpitas City Hall
- 6. The name of the sureties upon the bond of the Contractor for said work of improvement is: First National Surety, Bond No. 6051293
- 7. Said work of improvement was accepted by the Milpitas City Council as completed on January 21, 2003.

I, the undersigned, declare that I am the RDA Project Manager of the City of Milpitas and am authorized to execute the foregoing Notice of Completion and this Verification thereof. I have read the foregoing Notice of Completion. I declare under penalty of perjury that the foregoing Notice of Completion is true and correct. Executed on \_\_\_\_\_ at Milpitas, California.

\*

Greg Armendariz, RDA Project Manager	
City of Milpitas	

NOTE: RECORD WITHIN 10 DAYS OF ACCEPTANCE WITH COUNTY RECORDER OF SANTA CLARA COUNTY

City of Milpitas
455 East Calaveras Boulevard
Milpitas, CA 95035
Attention: Office of the City Clerk

Record without fee under Section 6103 - Government Code State of California

59068 R

RESOLUTION NO. \_\_\_\_\_

# A RESOLUTION OF THE CITY COUNCIL OF THE CITY OF MILPITAS APPROVING INITIAL ACCEPTANCE OF MILPITAS CITY HALL PROJECT PROJECT NO. 8026

WHEREAS, the City of Milpitas has heretofore entered into a Contract with Sasco, for the electrical for Milpitas City Hall, and the City Hall Project Manager of the City of Milpitas has recommended acceptance of said improvement as completed in accordance with plans, specifications and approved change orders and correction lists, and in accordance with the final inspection of said City Hall Project Manager.

NOW, THEREFORE, BE IT RESOLVED that the City Council of the City of Milpitas does hereby accept said improvement as completed on this 21 day of January, and does hereby authorize and direct the City Hall Project Manger \_\_\_\_ of the City of Milpitas to file a Notice of Completion in accordance with the provisions of Section 3093 of the Civil Code of the State of California, and does hereby authorize and direct the City Hall Project Manager to file a Certificate of Completion in accordance with the provisions of Section 4005 of the Government Code of the State of California, if said work was by day's labor or force account. The penal sum of the faithful performance bond securing said improvement may be reduced to the sum of \$3,996,111.90 upon request of principal and surety, said penal sum as reduced to apply from the date of completion and acceptance of said improvements and to extend for the balance of the term of said bond, provided that said term shall not be less than one year.

	PASSED AND ADOPTED this	day of	, 20, by the following vote:
	AYES:		
	NOES:		
	ABSENT:		
	ABSTAIN:		
ATTE	EST:		APPROVED:
		,	
CL 11 TO	N. L. J. O'. Cl. J.		Jose S. Esteves, Mayor
Gan E	Blalock, City Clerk		Jose S. Esteves, Mayor
APPR	OVED AS TO FORM:		
Stever	n T. Mattas, City Attorney		

-1-

Resolution No. \_\_\_\_

City of Milpitas 455 East Calaveras Boulevard Milpitas, CA 95035 Attention: City Engineer

Record without fee under Section 6103 - Government Code State of California

### CITY OF MILPITAS

A A CONTRACT BASE OF AS

### NOTICE OF COMPLETION

(Civil Code Section 3093)

### NOTICE IS HEREBY GIVEN:

- 1. On or about April 25, 2000, City of Milpitas, a municipal corporation of the State of California, whose address is City Hall, 455 East Calaveras Boulevard, Milpitas, California, 95035 (as owner) entered into a contract for work of improvement, to wit:
- 2. A description of the site of which the City is owner for said work of improvement is City of Milpitas, Santa Clara County, California, more particularly described as: City Hall Project, Project No. 8026
- 3. The nature and interest or estate of the City as owner of said site is in fee: Milpitas City Hall
- 4. The name and address of the original contractor is: SASCO, 1600 Memorex Drive, Santa Clara, CA 95050
- 5. A general statement of the kind of work done or materials furnished to the City is as follows: General Electrical for Milpitas City Hall
- 6. The name of the sureties upon the bond of the Contractor for said work of improvement is:

  American Home Assurance Company, Bond No. 00-251-189
- 7. Said work of improvement was accepted by the Milpitas City Council as completed on January 21, 2003.

\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*

I, the undersigned, declare that I am the RDA Project Manager of the City of Milpitas and am authorized to execute the foregoing Notice of Completion and this Verification thereof. I have read the foregoing Notice of Completion. I declare under penalty of perjury that the foregoing Notice of Completion is true and correct. Executed on \_\_\_\_\_ at Milpitas, California.

Greg Armendariz, RDA Project Manager City of Milpitas

NOTE: RECORD WITHIN 10 DAYS OF ACCEPTANCE WITH COUNTY RECORDER OF SANTA CLARA COUNTY

59068 R -2- Resolution No. \_\_\_\_\_

### City Hall Project

### Proposed Change Orders for Council approval - January 21, 2003

		UOI DE OE	UNBOUGHTS	Funding	CIP PROJECTS		PROJECT
Change		HOLDS OR	CONBOUGHIS	OTHER	CUP PROJECTS	- 50	NTINGENCY
Order#	Description	amount	Description	amount	CIP project description		amount
				Contingend	  cy as of Jan 10, 2003	<b> </b>	313,878
			(incl		arnings of \$233,000)	`	<b>, - · · ·</b>
Propos	sed Change Orders				<del> </del>		
	CORNER OFFICE		<del></del>	<del></del>			
1	Installation of work surface station 227						
	Installation of Work durings Station 227		<del> </del>		<u> </u>	3	92
	DIVISION TWO CONSTRUCTION		<u> </u>				
2	Rescind Change Order 12 for overcharges from					s	151,222
	March 21, 2001 to January 26, 2002.					ļ <u> </u>	101,222
3	Credit for deletion of fire extinguishers (provided by another contractor)					\$	(11,760
4	Misc additional general conditions labor provided					\$	12,508
	after move-ln.					Ψ	12,000
	INSULCRETE		ļ				
5	Additional trip to install roof (remobilization from			-		<b> </b> -	
5	Southern Cal.)		,	]		\$	2,500
	ONE WORK PLACE						
6	Additional Lobby furniture					\$	10,772
7	Additional 48" round table for meeting room			<u> </u>	ļ	\$	774
8	Additional display cases		<u> </u>			\$	6,704
	PACIFIC WATER ART			<u> </u>			
9	Cost to locate leak at water feature.					\$	3,617
	COOK TO IDEATO FOR THE TAIL OF					*	0,011
	ROYAL GLASS			1		j	· · · · · · · · · · · · · · · · · · ·
10	Credit for damage to 4th floor roof by crew during					\$	(12,543
	SERVICE METAL PRODUCTS					ļ	. <del></del>
11	Rescind previous cco approved by Council, because staff has requested additional restroom shelves.					\$	480
	SASCO			·		<u> </u>	
12	Additional Type F34A track and fixture heads at 3rd		<u> </u>	<del> </del>		\$	4 746
	Floor Rotunda.			ļ		<u> </u>	1,719
13	Plug weep hole and seal lens of Type EF3 light fixture at jet fountain.			1		\$	402
14	Change light fixture at Council Gallery; delete Type			† · · · · · · · · · · · · · · · · · · ·		1	<del></del>
	F22 over doors and provide Type F16 downlights.			İ		\$	(728
15	Delete change order 34 Adjust electrical due to			-		1	
10	removal of ceiling tile			<u> </u>		\$	(4,528
16	Delete change order 87 for incomplete installation		′			\$	(3,173
17	of HiD readers on the balconies  Back charge for use of scaffolds			-		\$	(1,743
18	Back Charge for ceiling tile damage			-		\$	(2,034
	SILICON VALLEY SECURITY			<u> </u>			
19	Additional expenses for City half security services					\$	20,000
	thru December, 2002.			<del></del>		1-	
	Cost Sub-totals	\$ .		\$ -	····	\$	174,281

[		HOLDS OR UNE	OUGHTS	OTHER CIP PRO	JECT8	CON	ROJECT TINGENCY
Change Order	Description	emount	Description	emount	CIP project description	١.	mount
	per production and the period of the period			project Con		_	,582,106
					COOle eries to March 4, 2004	١.	10 70
İ				ļ '	CCO's prior to March 1, 2001	\$	48,73
	A & B PAINTING	<u> </u>					·
	Credit for deleting paint in gerege Credit for deleting sealing for Stone (work done by	(12,879)	<u> </u>	<u> </u>		<del>-</del>	
	Carrara)	(7,842)			-,		
	Paint exterior and interior of trash enclosure Sand, prime and paint Community Center and	2,505		<del> </del>			
- 5	Library signs Added changes per builetin 20	\$ 3,495 \$12,939	Paint Holds	<u></u>	<u> </u>	<u> </u>	
6	Added changes per bulletin 7	\$2,793					·
ļ	Paint council chambers ceiling & misc patching not included in the plans	\$1,411				L	
8	Repaint Restrooms on 1st & 2nd floor (backcharge to Rollie French)	\$1,589					
9	Paint 4th floor, including rooms 407 & 409, not						
10	included in the plans  Paint Mock up for level 5 finish on 3rd floor retunds.	\$1,849				<u> </u>	
	Spray primer on 2 walls at 1st & 2nd floors for level	\$627 \$ 263		ļ <u>-</u>			
	4th finish			ļ <u> </u>			
	Prime & paint low wall partition in room 155  Prime and firish added walls by stairwell #4 on 2nd	\$ 175 \$ 563	ł	<b> </b>	<u></u>	<del> </del>	
	floor					<u> </u>	
	Repaint wall after re-taping of the wall on 2nd floor south end. (Backcharge to Rollie French)	\$ 3,761		<u>-</u> -			
15	Prime and re-paint patched walls on 3rd floor after plaster crew fixed wall finish problems (Backcharge	\$ 4,354				l	
- (	to Rolle French)						
16	Repaint walls @ council member offices due to TV cable relocation (Backcharge to Kelly	\$ 657					
	Communications)	\$ 2,915	<b></b>	·		<b> </b> -	
17	Repaint interior walls at 2nd and 3rd floors (change accent color to white) as requested by City	2,815	]	1		1	
18	Repaint walls @ mayor's office after relocation of	\$ 316	<del> </del>		<u> </u>	<del> </del> -	
	electrical outlets		ļ				
	Sand, prime and finish corridor @ council chambers due to trade damage	\$ 480		l		l	_
20	Prime & finish @ room 103C and mens & women restrooms due to trade damage	\$ 796		1			
21	Prime & finish light boxes at rotunda	\$ 325					
22	Masking and covering carpet @ 2nd and 3rd floors. To protect from damage	\$ 987					
23	Touch up and finish taping due to lack of manpower	\$ 125		\			
24	thackcharge to Rollie French) Patch wall and touch up 2nd, 3rd, and 4th floor due	\$ 125	<del> </del>	<b></b>		$\vdash$	
26	to trade damage Repaint rotunda due to repatching (Back charge to	\$ 3,118	ļ <u></u>	ļ		├	
	Rollie French)						
26	Reprime rotunda ceiling (Back charge to Rollie French)	\$ 1,037		ļ			
27	Repaint areas at stair #4 & 7 due to steel work	\$ 191					
	(Backcharge to Metal Air) Paint interior of elevator lobby at garage. Work was	\$ 725			<u> </u>		
20	not included in contract scope.  Paint corridor at rear of Council Chambers Sand, re	\$ 472	ļ	ļ		ļ	
	prime, and finish due to trade damage	ļ				<u>l</u>	
30	Repaint 4th floor low walls due to design modifications and trade damage by Rolle French.	\$ 5,396	İ	ĺ	!		
	Trade damage will be backcharged to responsible contractor	ĺ	ĺ	1		ĺ	
	Prime and paint additional areas at the 4th floor.	\$ 931					
32	Paint library exterior. Work includes prep work, cowerwashing, doors, flashing, and handrailing.			\$ 26,533	Misc City Bidgs. (#8135)	l	
33	Paint Community Center exterior. Work includes	j			Comm. Center Renovation		
	prep work, powerwashing, doors, flashing, and handrailing.			\$ 36,798	(#8102)		
34	Repair surface of trash enclosure, paint top and exterior skies with elastomenc paint	\$ 3,906				ĺ	
35	Cleaning of taping mud and fireproofing from steel a			1			
38	Stair #6. Cleaning of concrete from Stair #6	\$ 370 \$ 414				_	
37	Trade damage throughout the building, (Some of these costs will be backcharged to responsible						
<del></del>	contractors )	\$ 20,000	ļ				
	Adjustment to psinting touch-up allowance due to labor rate increase as of July 1, 2002	\$ 1,141				_	
39	Painting touchup at various locations after move-in.			1	}	\$	13,0
	ACCO				<del>                                </del>	<del> </del>	
5600-001	Fountain Equipment Room HVAC			\$ 14,605	Pond Renovation (#8141)		
5600-002	Changes required in duct layout and duct size due to ceiling clearances (\$69,852)	9	Į	1		ļ	
	Revisions to Boiler Room Layout and ductwork to	ŀ	ĺ	1		1	
	accommodate 4th floor revisions (\$21,330) Elevator Equipment Room revised to include a/c				İ	1	
	supply (\$11,876) Add Stair Pressurization at Stair #5 (\$5,752)		,				
	Revisions to ductwork in Gallery (located behind	ł	}	}	1	-	
	chamber room) (\$9670) Garage Exhaust improvements included added a						
	second exhaust fan to provide better ventilation (\$10.923)	1		1			
	Air Distribution revised to provide better temperature	1	1			l	
	and comfort at Main entrance, (\$4,151)	1	1	}		1	
	Revised straight slot diffusers to Radius Slot	1					
	Offusers at Rotunda for improved aesthetics (\$1,326)	1				1	
	Delete Hot Water Colls at A/C Units as Value	1					
	engineering. ( -\$8,640) FM 200 System in the Main Telecom Room- Add	1	1	1		j	
	two fire/smake dampers in telecom room. (\$2,530)			ļ		1	
	Add Outside Air at Garage Lobby and Ftn. Pump						
	Rm. Additional ductwork & fire smoke dampers required at fountain pump room & garage lobby.			1		\$	135,4
			1	1	1	1	

## City Hall Project Change Orders and Agreement amendments

· · ·	[	HOLDS OR UNB	QUGHTS	OTHER CIP PROJ	EGT8	COMIN	GENCY
Change Order	Description	amount	Description	amount (	CIP project description	<b>A</b> TOO	nunt .
5600-003	Design & installation of 4th floor air distribution					s	52,053
5600-004	system. Furnish & install one control panel that will provide	\$18.652	HVAC holds	l		<u>-</u>	
1000-004	power controls to the operable (motorized) louvers	¥,4,-42	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	1			
	on the 4th floor and top of the rotunda. This louver is part of the building natural ventilation system, where		ŀ	!!			
	the lowers in the intunda and fourth floor open and			1	į		
	close based on climate differences between Interior			ĺĺ	ĺ		
'	and extenor of the building.		,	!!!			
5600-005	Furnish & Install a sister control system for the	\$8,882	HVAC holds				
	natural ventilation touver system, including all the		l	1			
	wiring and monitoring devices to monitor wind and rain. This control module works with the main control		1				
	panel and will override the louver main control panel		į				
	based on adverse weather conditions,		ļ				
5600-006	Furnish and install duct sleeves in garage ventilation	\$3,343	HVAC holds	<del> </del>			
	ductwork. Sleeves are necessary to provide drain			<b>i</b> !			
	lines through the very large garage duct.		i	I	1		
5600-007	Changes to HVAC system on rooms 187 & 168 to						
5600-008	convert to a single larger commission room.  Additional HVAC diffusers to room 240, in order to	\$3,281	HVAC holds	<del> </del>			
5800-008	conven storage space to office space	\$1,596	HVAC holds	l1			
5600-009	Install duct under beam @ council chambers per SK-						
rean ded	221	\$5,632 \$ 5,000	HVAC holds				
5600-010 5600-011	Added weather station to control buyer operation.  Furnish and install ALC Alert - which is a Paging						
	system for critical HVAC alarm.	\$ 5,000		ļ			
5600-012	Add wind direction indication and rain transmitter to Weather Station. This will assist in controlling the		1				
	louvers in the Rotunda and 4th floor,	\$ 3,245	<u> </u>	<b> </b>			
5600-013	Install four HVAC supply grilles @ 4th floor. Work						
	required due to temporary construction office use.	\$ 1,600		<u>                                      </u>			
5600-014	Install Make up water piping for condensation on						
5600-015	installation of Reheat Coil at Council chambers	\$ 4,363 \$ 6,971	<del> </del>	<del> </del>			
5600-016	Relocate cump room fan coil unit due to field	9 3,07					
	conflicts.	\$ 5,895		<b> </b>			
5600-017	Relocate Audio/Visual room fan coil units due to conflicts.	\$ 2,524		1			
5600-018	Revise ductwork/registers due to ceiling changes to						
	Telecom rooms Ceilings revised as value	\$ 3,550	ļ .				
5600-019	engineering revision  Addition of elevator vent and flashing which were not	9 0,000	·				
	shown on plans	\$ 3,215	ļ				
5600-020 5600-021	Relocate slot diffuser @ Council Gallery Stand-by Time during Council Meeting of 10/08/02	\$ 1,253	<del> </del>		<del></del>		64
3000-021	Statio-by Tittle during Cooker mastering of Torotace		1			\$	04
	ALLIED FIRE PROTECTION		1				
1	Adjust Fire sprinklers due to ceiling changes on all 4	\$ 26,000	<del> </del>	ļ ·			
	floors	,	<u> </u>	-			
		<b></b>					
	AQUA PROOF, INC		<del></del>				
1	Misceillaneous caulking of floors, walls, windows, etc.						30
				·			
	BAINS MOVING SERVICES CORP		ļ	ļ			
2	Moving services to empty out Great Mall furniture and other items left behind after occupation of new	1				S	11,12
	City Hall		J	ļ			
	BT MANCINI				. <del></del>		
	1 Credit for deleting Floor Sealing from contract	(130,955	)				
	2 Sand, vacuum and expoxy seal floors at 16 rooms	\$ 4,544					
	(telecom and electrical) 3 Furnish & install waterproof membrane at		Flooring Hold	15			
	mechanical room	\$ 3,750	Flooring Holo	)s			
	Compensation for carpet and flooring labor rate		FF&E holds				
	Compensation for crane rental to hoist carpet and	\$3,655	FF&E holds			I	
	5 flooring materials	\$1,760	1,		,	ļ	
	6 Overtime to accelerate carpet installation prior to				· —	l -	
	strike. This prevented delays and additional costs which would have been necessary to remobilize	1		1	1	(	
	other trades due to strike.	\$ 3,896	<u> </u>			L	
	Furnish and install VCT at all stairwell landings at the 1st, 2nd, and 3rd Floors, as well as, one (1) landing	1	1			l	
	at the 4th Floor and 1st Floor under Stairs.	1		1		l	
	7	\$ 4,624		-		1	
	8 Grout Float doorways and room 103  Extra work to float mortar at several places prior to	\$ 636	<u>'</u>			l	
	9 Installation of carper and VCT	\$ 11,910	)				
1	0 Installation of carpet on 4th floor and filing areas on 1st and 2nd floor	\$ 19,129	.	1	1	1	
	Credit for furnished and installed materials in Data	18,123		1		\$	(1,5
	I1 Room 364	ļ				_	
1	2 Change on carpet material for Council Chambers and 2nd floor hallways	1	,			\$	10,7
	3 Floating 4th floor & 2nd floor walkways					S	7
	4 Credit for damage to wood panels 15 Contract Savings after contract closure	- <del></del>		-	<del> </del>	\$	(23,2
	BBI ENGINEERING, INC.			J	ļ		
	Labor and materials to relocate an equipment rack in the Council Chambers rear projection room. Also	n	1	1.	Gity Hall Technology (Project		
	includes upgrading the audio/visual projector.		1	\$ 8,930	#8142)	1	
					ļ		
	Additional audio/visual microphone system & ceiling speakers, antenna, and misc. equipment for Council	ı	1	}		1	
	chambers and overflow room(pre-function area )	1		1	i		
	2	\$ 7,58	3	-	<del> </del>	<del> </del>	
	Credit for deletion of four plasma screens on council 3 gallery and lobby.	<u>'</u> L	_	(27,838	)		
	4 Build-Out Room 149 (Human Resources Conference	e	·	1		1	
	Room) to same level of functionality as other conference rooms. This includes furnishing and	1	-	1		ŀ	
	Installing projector & screen, and electronic white	1.		1	1	1	
	[board.	\$ 25,32	9		City Hall Technology Project	<b></b>	
	Furnish and Install brushed aluminum enclosure for						

, At we

Change Order		HOLDS OR UND	1	OTHER			CUN	TINGENCY
#	Description	amount	Description	umoun	t .	CIP project description		mount
6	Changes to Room 219: Provide sliding rack which was to be installed within furniture in lieu of shweeled equipment rack with plexiglas door.			ş	2,719	City Hall Technology Project (CIP #8142)		
7	Alterations to floor boxes for Conference Tables.			-		CIP #8142 City Hall		
8	Overtime premium in order to expedite intaliation of			3	2,528	Technology	s	13,33
	audio visual equipment						Ť-	7-1
1400-01	CARRARA MARBLE Solaris Stone cladding upgrade						3	13,80
400-02	Demo and frame window opening at 3rd Floor Grid.	\$ 2,248						
4400-03 4400-04	Furnish & install limestones sits per Sketch 86. Furnish and install grante tiling on waterfall face			-			\$	1,58
4400-05	(\$32,148) and welr cap (\$14,100) Provide grooves and expoxy grout at grande stairs at	46,248						
1400-06	Rotunda. Furnish and install additional stone veneer and	\$ 5,035	Stairs Holds			····	l	
1400-07	cutting existing stones at north balcony Preparation of additional structural calculations for	\$ 1,700 \$ 7,950	Stone Holds					
4400-08	added structural framing by Royal Glass Additional labor provided to cut 11 holes for	\$ 990						· · · · · · · · · · · · · · · · · · ·
4400-09	Additional electrical outlets on the exterior stone Additional labor to move materials into basement for	\$ 1,716		_				
4400-10	storage. Two weeks rental of scissor lift to install stone on the	\$ 435						
4400-11	west side of building due to miscoordination Changes to wall height on 2nd and 3rd floor	40.007	Drywall Holds					
4400-12	Deletion of Change order No. 6 (Grante Tiling on	\$2,067 (\$46,246						
4400-13	Water fall face) Additional stair work per detail A7,19 dated 07/02/02	\$ 3,925	····					
4400-14 4400-15	Add Ceramic Tile at deck 233  Cut and float restroom floors at 116, 117, 205, 206,	\$ 1,440		<u> </u>			<u> </u>	
4400-15 4400-16	225, 226, 303, 304, 311,312, 403, ad 402.	\$ 7,470 \$ 2,417		ļ				· · · · -
4400-10	Overtime (Sat. 08/10/02) to set stair treads and risers, set Lobby pavers, and grout interior. Cost to be recovered from other contractor.	2,41/		ľ			ĺ	
4400-17	Cut and float restroom floors at 116, 117, 205, 206, 225, 226, 303, 304, 311,312, 403, ad 402,	\$466	i		· · · · · · ·			
	PREVIOUSLY REQUESTED FROM COUNCIL ON 05/06/02 - Additional cost required, cost difference	ļ						
4400-18	requested only.  Overtime (Sat. 08/03/02) to set Lottoy gavers.	4.461						
4400-19	Overtime (Sat. 08/10/02) to set granite on the rotunda, stairs and in the lobby (Note: Date should	, 41,921						
4400-20	Le 98/17/02  Exterior wall sheathing between soffits and ceiling	3,872		ļ —			ļ	
	around the 1st Floor below the Council Chambers.	12,590						
4400-21	Grout mock-up at exterior pavers after approved color was relected.	\$ 520						
4400-22	Float battered wall at outside radius of South Plaza to facilitate placement of limestone face	\$ 5,040						
4400-23	Overhead and Profit compensation for exterior wall sheathing between soffits and ceiling around the 1st						s	1,25
4400-24	Floor performed by their subcontractor.  Claim Settlement for additional costs incurred due to						ļ	
	project delays and labor increases						\$	57,44
	CONCO						_	
3300-07 3300-08	Manifit additional concrete reinforcement and bulletin	\$ 239,264	Gen. Cond.	<b> </b>	-		s	159,00
3300-09	revisions Bracing for backfill - requested to accelerate						\$	20,59
3300-10	construction Subgrade Additional work - form and place additional						-	
	footing and slab concrete due to additional excavation to remove wet subgrade.						\$	6,99
3300-11	Lightweight concrete at topping slabs - changed concrete mix design from regular weight concrete to	\$ 3,023	Concrete hold	1				
3300-12	lightweight concrete Additional Garage Ramp reinforced concrete -	J	<del> </del>					
	provides for increase in excavation, baserock, concrete, reinforcement, retaining wall heights, for			İ				
	design revisions to garage ramp. Design revisions are necessary to mitigate high groundwater.	1					\$	192,3
	(\$35,000 of this amount is for Ferma's excavation PCO 037-002). Total approved by Council is							
3300-13	\$227,315. Additional concrete and reinforcing at various		<u> </u>				\$	12,5
3300-14	building locations  Additional housekeeping pads @ mechanical pump		<del> </del>	5	3,502	Pond Renovation #8141		
3300-15	room  Balcony Topping slab Fill Revisions - furnish & install Burke LPL epoxy adhesive, increase fill thickness		†	<u> </u>	······································			
	from 1/2° to 2° at drains, change from lightweight to		,	1			s	11,0
	regular concrete, high early strength mix design and premium labor to finish balconies							
3300-16	Additional field costs and concrete cost escalation due to extended project schedule, for work					<u> </u>		
	completed. This includes additional superintendent labor, field equipment and tools furnished for a			1			5	46,2
3300-17	lador, ned equipment and tools runnished for a longer project schedule.  Daily Extra work orders from March 2001 to	ļ					-	
~avv-11	September 2001. Additional labor and materials wa provided due to field revisions, through daily work	s					\$	43,3
3300-18	orders  Deductive change order to eliminate concrete curb			ļ			+	
	and wall at patio area. This work will be added to			1			\$	(5,0
	JJR Construction and eliminate a delay claim.		1					
3300-19	JJR Construction and eliminate a delay claim.  Deductive change order to eliminate remaining upper	ļ <u> </u>	-	├			$\vdash$	
3300-19	1	<del> </del>					5	(10,2

		HOLDS OR UNE	опонтя	OTHER CIP PRO	JECTS .		ioject Iingency
Change Order		l	<b>D</b>		CID weeks at described		,
3300-21	Description  CMU Work in garage for elevator, telecom and	nmount	Description Concrete holds	amount	CIP project description		nionut
	fountain rooms.	\$ 10,553	Cultified INIXI				
3300-22	Disencumber cost savings in contract.	(\$80,251)	<b></b>				
					I		
	Additional structural supports for roll up grilles.	\$1,550	Misc. metal				
			hoids				
	Repair roll-up door at garage due to damage by others.	2,120					
	CORNER OFFICE				L		
1	Furnish and install custom cabinet for Fire Protection section workspace.	\$727	FF&E holds			_	
2	Furnish and Install 5 additional stations fo	\$15,440		_			
	Engineering department Additional cost to provide union labor for installation	\$5,000	FF&E holds				
	of office workstations		FF&E holds				
4	Storage fees for office workstations from January 2002 to July 2002, due to extended project schedule	\$31,930	FF&E holds				
			ecas Esta				
	Furnish & install 153 keyboard trays for workstations and cashier stations	\$37,413	FF&E holds				
6	Furnish & install high density filing cabinets for Fire Prevention (2,423 Inches of filing) & Engineering		FF&E holds			Ī	
	(15.634 inches of filing)	\$33,888					
7	Furnish & install one additional workstation for building department.	\$3,820	FF&E holds		ĺ		
8	Additional electrical parts for workstations to provide	40,020					
	for printers, copiers, and fax machines to be fed by stations	\$ 4,232					
	Field fit of keyboard tray to private office desks	\$ 214					
10	Furniture delivery to 2nd Floor, additional cost for additional delivery due to coordination with work at						
<del></del>	site Modification to layout in Room 342.				ļ	<u> </u>	
112	Additional delivery charges for 3rd Floor Bid was for						
	brining soft trailers delivery. Had to use smaller	ĺ	ĺ	ſ			
13	trucks and forklift Additional costs due to separate furniture delivery to	\$ 1,854					
	2nd floor. This is a direct cost impact due to the carpet layers' strike.	\$ 1,237					
14	Furniture modifications to Room 342	. 4					
	(wordprocessing.) This includes additional partition panels and labor to relocate workstations away from						
	windowdue to a design error						
16	Add 129 task lights for workstations.	\$ 2,590 18,679					
16	Pack panels for high density filing system.	\$ 836					
17	Field changes at 3rd floor. Additional office modular changes					\$	1,82 9,20
19	Increased Sales Tax from 8% to 8 25%					\$	1,27
20	Changes to Secretary Stations in Administrative Suite, including additional files and shelving, and					ş	5,70
	expansion of station				<u> </u>		
21	Install carget on high density filing system				1	\$	92
1000-01	DIVISION TWO CONSTRUCTION Install Doors, Frames, Hardware - provide labor and						
1000-01	equipment to install doors, frames and hardware	\$ 55,386	Doors / Frames				
1000-02	furnished by City	·	France				
	Install new Fire Hydrant at Calaveras Blvd dinveway;	1		ŀ		ļ	
	Safety upgrades to stormdrain lift station,						
	Upsizing of on-site drainage pipes and						
	Increase area drain inlet sizes (total change order = \$258,000)	\$ 141,970	Sitework			s	116,00
1000-03	Mass Excavation, Earthwork, Spolls Removal for						
	stework. This work is for all the site improvements.	\$ 157,000	Earthwork	\$ 169,269	Pond Renovation (#8141)		
	including pend and walkways. Yetal approved ≈ \$326,289						
1000-04	Install ramp storm drainage pipe and manholes,	6 00.000	ļ .				
	deleted from Preston Pipeline contract and Ferma's contract	\$ 28,000					
1000-05	Furnish and install rough carpentry work for roof						
	formwork (\$32,000); provide temporary chainlink fencing (\$5,947); provide credit of \$7,000 to delete	\$ 31,566					
	furnish and install conference room whiteboards)						
1000-06	Total is \$31,566 Provide and Install 12 mil. Hippwrap	\$ 5,850			<del> </del>		
1000-07	weathercroofing at the 4th floor skylight. Acoustrical Insulation @ Council Chambers (The	<del> </del>			ļ		
1000 01	work included tacking and gluing down 1*, 1 1/2 lbs.					l s	18,2
	Oensity acoustical insulation on the floor of the council chamber floor plenum.)					ľ	10,2
1000-08	Rain and Weather Protection, Including materials to	\$ 9,091	General		<u> </u>		
		ſ	Condition Holds	ĺ	1	ĺ	
	protect site & Interior from weather; equipment; and labor		1.5.50				
1000-09	labor	\$ 4,500	C		1	Ì	
1000-09	labor Additional 300 feet of Fence Panels, Privacy Screen Signage for Traffic Control, Supervision and		General Condition	1			
	labor Additional 300 feet of Fence Panels, Privacy Screen	,				<u> </u>	
1000-09 1000-10	labor.  Additional 300 feet of Fence Panels, Privacy Screen Signage for Traffic Control, Supervision and Plannca, and Miscolaneous Short Expenses.  Additional Roof Blocking, Including additional Fire		Condition Holds General			_~	
	labor  Additional 300 feet of Fence Panels, Privacy Screen Signage for Traffic Control, Supervision and Planning, and Miscellaneous Shop Expenses  Additional Roof Blocking, Including additional Fire treated 4-%5" & 2"x10", plywood for revised roof ad	,	Condition Holds General Condition				
	labor  Additional 300 feet of Fence Panels, Privacy Screen Signage for Traffic Control, Supervision and Planning, and Miscellaneous Shop Expenses.  Additional Roof Blocking, Including additional Fire treated 4"x6" & 2"x10", physood for revised roof ad additional Carpenter labor for Roof Blocking.	\$ 12,668	Condition Holds General				
1000-10	labor.  Additional 300 feet of Fence Panels, Privacy Screen Signage for Traffic Control, Supervision and Plannan, and Miscellaneous Shop Expenses.  Additional Roof Blocking. Including additional Fire treated 4*x6* & 2*x10*, plywood for revised roof additional Carpenter labor for Roof Blocking.  Gazebo Demolition. Including exploratory demolition.	\$ 12,668	Condition Holds General Condition				
1000-10	labor.  Additional 300 feet of Fence Panels, Privacy Screen Signage for Traffic Control, Supervision and Signage for Traffic Control, Supervision and Miscolaneous Shop Expenses.  Additional Roof Blocking. Including additional Fire treated 4*x6* & 2*x10*, plywood for revised roof additional Expenser labor for Roof Blocking.  Gazebo Demolition Including exploratory demolition and hazard verificalion, protective foncing in countryard, craine and negling, broth crew, debris box	\$ 12,668	Condition Holds General Condition			\$	14,9
1000-10	labor.  Additional 300 feet of Fence Panels, Privacy Screen Signage for Traffic Control, Supervision and Plannica, and Miscolaneous Shop Expenses.  Additional Roof Blocking. Including additional Fire treated 4*x6* & 2*x10*, phywood for revised roof ad additional Carpenter labor for Roof Blocking.  Gazebo Demolition. Including exploratory demolition and hazard verification, protective fracting in courtyard, carea and niggling, torch row, debits box and off-hault (16 his trucking @\$72 per hour for hault.)	\$ 12,668	Condition Holds General Condition			s	14,9
1000-10 1000-11	labor.  Additional 300 feet of Fence Panels, Privacy Screen Signage for Traffic Control, Supervision and Plannon, and Miscellaneous Shon Expenses.  Additional Roof Blocking, Including additional Fire treated 4166 & 21x10°, phywood for revised roof ad additional Carpenter lebor for Roof Blocking.  Gazebo Demolition Including exploratory demolition and hazard verification, protective foncing in courtyard, crane and nggling, torth crew, debris box and off-habit (16 his strucking @\$72 per hour for hauf off and 35 yard debris boxes @ \$700 each), plaster patch on existing Struco, and demolition labor hours	\$ 12,668	Condition Holds General Condition Holds			s	14,9
1000-10	labor  Additional 300 feet of Fence Panels, Privacy Screen Signage for Traffic Control, Supervision and Planning, and Miscellaneous Shop Expenses  Additional Roof Blocking, Including additional Fire treated 4*36* 8 2*x10*, plywood for revised roof additional Carpentar labor for Roof Blocking.  Gazebo Demolition Including exploratory demolition and hazard verification, protective forcing in courtyard, crane and negling, broth crew, debris box and off-haul (16 hrs trucking @\$72 per hour for haul off and 35 yard debres boxes @ 3700 each), plaster	\$ 12,668	Condition Holds General Condition Holds			s	14,9
1000-10 1000-11 1000-12	labor  Additional 300 feet of Fence Panels, Privacy Screen Signage for Traffic Control, Supervision and Planning, and Miscellaneous Shop Expenses  Additional Roof Blocking, Including additional Fire fuested 41x6* & 21x10*, plywood for revised roof ad additional Carpentar Labor for Roof Blocking.  Gazebo Demolition Including exploratory demolition and hazard verification, protective forcing in courtyard, crare and reging, broth crew, debris box and off-haul (18 his trucking @\$72 per hour for haul off and 35 yard debris boxes @ \$700 each), plaster patch on existing Stucco, and demolition labor hours Additional debris boxes, cost to be shared and	\$ 12,668	Condition Holds  General Condition Holds			s	14,97
1000-10	labor.  Additional 300 feet of Fence Panels, Privacy Screen Signage for Traffic Control, Supervision and Plannan, and Miscelaneous Shop Expenses.  Additional Roof Blocking. Including additional Fire treated 4*x6* & 2*x10*, plywood for revised roof additional Expenser labor for Roof Blocking.  Gazebo Demolition. Including exploratory demolition and hazard verification, protective foncing in courtyard, crace and reging, broth crew, debris box and off-haul (18 hrs trucking @\$72 per hour for haul off and 35 yard debris boxes @ \$700 eacth), plaster patch on existing Stucco, and demolition labor hours Additional debris boxes, cost to be shared and deducted from other contractors. 40 boxes @(35)	\$ 12,668	Condition Holds General Condition Holds General Candition			\$	14,9
1000-10 1000-11 1000-12	labor.  Additional 300 feet of Fence Panels, Privacy Screen Signage for Traffic Control, Supervision and Plannana, and Miscolaracous Shop Expenses.  Additional Roof Blocking. Including additional Fire treated 4*x6* & 2*x10*, plywood for revised roof additional Capenter labor for Roof Blocking.  Gazebo Demolition. Including exploratory demolition and hazard verification, protective foreign in courtyard, craine and reging, torich crew, debris box and off-haul (18 hrs trucking @\$72 per hour for haul off and 35 yard debris boxes @\$700 each), plaster patch on existing Stucco, and demolition labor hours. Additional debris boxes, do \$700 each), plaster patch on existing Stucco, and demolition labor hours. Additional debris boxes, do \$100 each each each each each each each each	\$ 12,668	Condition Holds General Condition Holds General Candition			s	14,9

Fores

stien back to City for overcharges on monthly a from April 2001 through December 2001. iifs for elevetor No. 1 unity Certier Roof drains tie-ins to site drain gunder beams @ library& Community Certier mal labor & mail used for SWPPP work, tie and offhaul spoils for pond perimeter wall s. Its drains @ stage area in order to improve go of this area. underlands area in order to improve go of this area. It is a consistent behind waterfall and retaining rail door installation and charges. It is below the stage area in order to improve go of this area. It is below the stage area in order to improve go of this area. It is below the stage area in order to improve go of this area. It is below the stage area in order to improve go of this area. It is of this area. It is of this area. It is one the stage area in order to improve go of this area. It is one the stage area in order to improve go of this area. It is one the stage area in order to improve go of this area. It is one to the stage area in order to improve go of this area. It is one to the stage area in order to improve go of this area. It is the stage area in order to improve go of this area. It is the stage area in order to improve go of this area. It is the stage area in order to improve go of this area. It is the stage area in order to improve go of this area. It is for order for general conditions labor aterials.  RPRISE ROOFING gent wall primer in A install fashing for 2nd & 4th floor decks. It is install roof system above Council bers, including 2-1/27 rigid insulation (R19)  over existing concrete pool deck. 4 by felt bu	7.113 29,764 \$ 8,236 \$ 10,000 \$ 8,000	Description	\$ 7,077 \$ 1,703	CIP project description  Pond Renovation (#8141)  Pond Renovation (#8141)	8.	mount
back to City for overcharges on monthly in from April 2001 through December 2001.  Iffiger elevator No. 1  unity Center Roof drains the his to site drain  quoder beams @ library& Community Center  mai labor & mait used for SWPPP work,  also and offfhaul spoile for pond perimeter wall  sets and offfhaul spoile for pond perimeter wall  sets drains @ stage area in order to Improve  10 of this area.  Subdrain system behind waterfall and retaining  real door installation and changes.  In concession of the changes attended to  10 of this area.  In the concession of the changes  10 of this area.  In the changes attended from passage  10 conforence Room hardware from passage  10 conforence Room hardware from passage  10 consistended in the changes attended  10 of the changes attended to  10 of the changes and building cleanup,  10 of the changes and building cleanup,  10 of the changes and general to  10 of the changes and  10 of the changes  11 of the changes  12 of the changes  13 of the changes  14 of the changes  15 of the changes  16 of the changes  16 of the changes  17 of the changes  18 of the changes  18 of the changes  18 of the changes  18 of the changes  19 of the changes  19 of the changes  19 of the changes  19 of the changes  10 of the changes  10 of the changes  10 of the changes  10 of the changes  10 of the changes  10 of the changes  10 of the changes  10 of the changes  10 of the changes  10 of the changes  11 of the changes  11 of the changes  11 of the changes  12 of the changes  13 of the changes  13 of the changes  14 of the changes  15 of the changes  16 of the changes  16 of the changes  16 of the changes  17 of the changes  18 of the changes  18 of the changes  19 of the changes  19 of the changes  19 of the changes  10 of the changes  10 of the changes  10 of the changes  10 of the changes  10 of the changes  10 of the changes  10 of the changes  10 of the changes  10 of the changes  10 of the changes  10 of the changes  10 of the changes  10 of the changes  10 of the changes  10 of the chan	\$ 8,238 \$ 10,000 \$ 110,000	Description	\$ 7,077	Pond Renovation (#8141)		
a from April 2001 through December 2001, iris for televator No. 1 unity Carder Rood drains te-les to site drain unity Carder Rood drains te-les to site drain g under beams @ library& Community Carder rail fabor & matt used for SWPPP work ate and offhaul spois for pond perimeter wall stands of the site of the site of the site of the site stands of the site of site of the site of site of the site of site of site of site of s	\$ 8,238 \$ 10,000 \$ 110,000					
unity Center Roof drains te-ins to site drain quoder beams @ library& Community Center in a labort & mait used for SWPPP work, the and offhaul spoke for pond perimeter wall \$ to drains @ stage area in order to improve to of this area. subdrain system behind waterfall and retaining rigid door installation and changes. e Conference Room hardware from passage locksets and changes/atkrations throughout. I show and materials for general conditions grouph carpentry, site and building cleanly, library and materials for general conditions in ough carpentry, site and building cleanly, library and materials for general conditions and general labor for miscellaneous items of fiter occupancy. I to pain hardware at Door 203X. Ing change order for general conditions labor aterials. RPRISE ROOFING tent wall primer. In & install Rashing for 2nd & 4th floor decks, In & install Rashing for 2nd & 4th floor decks, Including 2-1/2* rigid insulation (R19	\$ 8,238 \$ 10,000 \$ 110,000					
unity Center Roof drains te-ins to site drain quoder beams @ library& Community Center in a labort & mait used for SWPPP work, the and offhaul spoke for pond perimeter wall \$ to drains @ stage area in order to improve to of this area. subdrain system behind waterfall and retaining rigid door installation and changes. e Conference Room hardware from passage locksets and changes/atkrations throughout. I show and materials for general conditions grouph carpentry, site and building cleanly, library and materials for general conditions in ough carpentry, site and building cleanly, library and materials for general conditions and general labor for miscellaneous items of fiter occupancy. I to pain hardware at Door 203X. Ing change order for general conditions labor aterials. RPRISE ROOFING tent wall primer. In & install Rashing for 2nd & 4th floor decks, In & install Rashing for 2nd & 4th floor decks, Including 2-1/2* rigid insulation (R19	\$ 8,238 \$ 10,000 \$ 110,000					
g under beams @ Ibrary& Community Center nal labor & maif used for SWPPP work, the and offhaul spoke for pond perimeter wall is and offhaul spoke for pond perimeter wall is a drains @ stage area in order to improve to of this area. Subdrain system behind waterfall and retaining raif door installation and characes. The conference Room hardware from passage locksets and charages/atterators throughout.  I also and materials for general conditions to prough carpentry, site and building cleaning, thorytemoval of protection covers for various a raif general labor.  I also pain hardware at Door 203X. Important or the cocupancy.  I op pain hardware at Door 203X. Important or the community of the pain of the pain hardware at the community of the pain hardware at the pain of the pain hardware at the pain of the pain hardware at Door 203X. Important pain hardware at	7.113 29.764 \$ 8.236 \$ 10,000 \$ 8,000					
nal labor & mati used for SWPPP work, the and offhaul spoke for pond perimeter wall \$ 1 and offhaul spoke for pond perimeter wall \$ 1 and trains @ stage area in order to improve to of this area. Which is area. Which is area. Which is area. Which is area. Which is area. Which is area. Which is area. Which is area. Which is area. Which is area. Which is area. On the same properties of the control of the contro	7.113 29,764 \$ 8,236 \$ 10,000 \$ 8,000					
ate and offhaul spoils for pond perimeter wall is alins @ stage area in order to improve go of this area.  Buddrain system behind waterfall and retaining raif door installation and changes.  Conference Room hardware from passage tocksets and changes/attentions throughout a labor and materials for general conditions group carpentry, site and building cleanup, literal wall protection covers for various and general labor.  In all general labor for miscellaneous items of ter occupancy.  Lo panic hardware at Door 203X  ling change order for general conditions labor attentials.  RPRISE ROOFING  lent wall prime!  A install flashing for 2nd & 4th floor decks.  A install flashing for 2nd & 4th floor decks.   A install flashing for 2nd & 4th floor decks.   A install flashing for 2nd & 4th floor decks.   A install flooring 2-1/2* rigid insulation (R19	\$ 8,236 \$ 10,000 \$ 8,000					
s the drains (2) stage area in order to improve the drains (2) stage area in order to improve the drains (3) stage area in order to improve the drains (3) stage area in order to improve the drains (4) stage area (4) stage area (4) stage area (4) stage area (5)	\$ 8,236 \$ 10,000 \$ 8,000					
ag of this area.  bubtrain system behind waterfall and retaining rigit door installation and changes.  c Conference Room hardware from passage locksets and changes atterations throughout.  la labor and materials for general conditions, library moves of protection covers for various as and general labor for miscellaneous items of fission pounds and peneral labor for miscellaneous items of fission pounds and peneral labor for miscellaneous items of fission pounds and peneral labor for miscellaneous items of fission pounds and peneral labor for miscellaneous items of fission pounds and peneral labor for miscellaneous items of fission pounds and peneral labor for miscellaneous items of fission pounds and peneral labor for miscellaneous items of fission peneral conditions labor alerials.  RPRISE ROOFING peneral conditions labor attention and labor for peneral primer.  A install Rashing for 2 and 8. 4th floor decks.  A install Rashing for 2 and 8. 4th floor decks.  A install fixed postern above Council bers, including 2-1/27 rigid insulation (R19).	\$ 8,236 \$ 10,000 \$ 8,000		1,703	Pond Renovation (#8141)		
subdrain system behind waterfall and retaining right door installation and changes. Experience Room hardware from passage locksets and changes/atterations throughout. It is allow and materials for general conditions no rough carpentry, site and building cleanup, librity-moval of protection covers for various is and general labor for miscellaneous items of fiter occupancy. It to panic hardware at Door 203X ling change order for general conditions labor atterials. RPRISE ROOFING year wall prime! A install flashing for 2nd & 4th floor decks. h & install flashing for 2nd & 4th floor decks. h & install flooring 2-1/2* rigid insulation (R19	\$ 8,236 \$ 10,000 \$ 8,000					
a Conference Room hardware from passage locksels and changes/akerations throughout.  It is a labor and materials for general conditions my cough carpentry, site and building cleanup, libriviemoval of protection covers for various a rad general labor.  Inal general labor for miscellaneous items of fiter occupancy.  In a light part of the protection covers for various a rad general labor for miscellaneous items of fiter occupancy.  In a light part of the protection covers for various and general labor for general conditions labor alternals.  RPRISE ROOFING  Lent wall primer.  A install Rashing for 2nd & 4th floor decks.  A install Rashing for 2nd & 4th floor decks.  A install fixed posterm above Council bers, including 2-1/27 rigid insulation (R19).	\$ 10,000 \$ 8,000					
a Conference Room hardware from passage locksels and changes/akerations throughout.  It is a labor and materials for general conditions my cough carpentry, site and building cleanup, libriviemoval of protection covers for various a rad general labor.  Inal general labor for miscellaneous items of fiter occupancy.  In a light part of the protection covers for various a rad general labor for miscellaneous items of fiter occupancy.  In a light part of the protection covers for various and general labor for general conditions labor alternals.  RPRISE ROOFING  Lent wall primer.  A install Rashing for 2nd & 4th floor decks.  A install Rashing for 2nd & 4th floor decks.  A install fixed posterm above Council bers, including 2-1/27 rigid insulation (R19).	\$ 8,000 110,000					
the babor and materials for general conditions no rough carpentry, site and building cleanup, (Iboviennoval of protection covers for various and general labor for miscellaneous items of fiter occupancy.  The occupancy of the protection of the occupancy of the panch hardware at Door 203X, ling change order for general conditions labor attention.  RPRISE ROOFING tent wall prime!  A install flashing for 2nd & 4th floor decks.  A install flashing for 2nd & 5th floor decks.  A install flashing for store occurred bots, including 2-1/2* rigid insulation (R19)	110,000				<u>.</u>	
a labor and materials for general conditions rig rough carpentry, site and building cleanup, tion/removal of protection covers for various and general labor.  That occupancy, and present a protection of the fact occupancy, at the panic hardware at Door 203X, ing change order for general conditions labor aterials.  RPRISE ROOFING rent wall primer.  A install flashing for 2nd & 4th floor decks.  The install floof system above Council bers, including 2-1/2* rigid insulation (R19	110,000					
files occupancy  to panic hardware at Door 203X  ing change order for general conditions labor aterials  RPRISE ROOFING  tent wall primer.  A install Rashing for 2nd & 4th floor decks,  h & install froof system above Council  bers, including 2-1/2* rigid insulation (R19				į		
e to panic hardware at Door 203X, sing change order for general conditions labor aterials.  RPRISE ROOFING near the street of th					s	25,0
ing change order for general conditions labor aterials  RPRISE ROOFING  year wall primer  A install flashing for 2nd & 4th floor decks,  h & install floor system above Council  bers, including 2-1/2* rigid insulation (R19					\$	5.
RPRISE ROOFING  year wall prime!  A install flashing for 2nd & 4th floor decks.  A firstall flashing for bove Council  bors, including 2-1/2* rigid insulation (R19		1			\$	6,5
nent wall primer h & install flashing for 2nd & 4th floor decks, h & install roof system above Council bers, including 2-1/2* rigid insulation (R19		L			<del></del>	
nent wall primer h & install flashing for 2nd & 4th floor decks, h & install roof system above Council bers, including 2-1/2* rigid insulation (R19						
nent wall primer h & install flashing for 2nd & 4th floor decks, h & install roof system above Council bers, including 2-1/2* rigid insulation (R19						
h & install roof system above Council bers, including 2-1/2* rigid insulation (R19	647 170				S	8,5
bers, including 2-1/2* rigid insulation (R19	\$17,470	Roofing holds				
over existing conclude root deck, a ply left but f, taper insulation for cricketing between , and 6" aluminum counter flashing.						
·	\$35,623					
ig repairs and additional final ply at the Upper Roof Deck only	\$ 37,629		1			
inal trip to waterproof around electrical panel	1				s	1,0
		<del> </del>			Ė	
ER						
es for fabrication and installation of the custor	,		\$ 91,985	City Hall Technology (#8142)		
rk for the Council Chambers Dias and Lecteri	·		4 01,000	City (fail facilitionary (#0142)		
rk changes as summarized in Bulletin #20 041, information desks in rooms 160 and 351 40),						
ew counter for room 349 (\$3,599)						
wall cap on the 4th floor (\$8,103) of these four change orders is:	1				s	23,7
h and install credenzas in 1st, 2nd, 3rd floor	7	1		CID 0400	]	
ence rooms. h and install solid wood radius wall cap and			\$ 20,924	CIP 8109		
wall base at guard rall rotunda walkway (2nd Revisions are based on RFI 554 and ies 170 A.B.C. th and install the following changes in the					\$	4,7
in allo instant the notwing changes in the gj chambers: Delete 554 p. ft. of wall paneling 930), Add 398 sq. ft. of acoustical waif ng and wood slates (\$40,586); Add wood doo at door 209 per RFI 531 (\$600). Total change is \$16,266.					\$	16,2
one acoustical panel at retunda (-\$2,257) an	d					
ign shop drawings for Reception Counter i 180 for changes (\$275). Total change order				1	\$	(1,9
,982)		<del></del>	<del> </del>	ļ	\$	1,3
e technician workstation per Sketch -131a, e public counter and information desk per	<u> </u>					
h 132c, 133, 135, 129c, 136a, 136b, 136c, Si   29b, 129c dated 1/17/02.	<sup>(-</sup>	1			\$	3,0
e work counter area to accommodate	1				5	1,
anding printer SK-137a, 137b.	-}		<b> </b>	<del> </del>		
luminum bar to four doors at back of Council			1		\$	1,3
bers per RFI 579 and Sketch 123e and 123f. le surround at open office #344 (under stair	\$4,041	Milwork holds	- <del></del>	<del> </del> -	<del> </del>	
sh & install a credenza at room 168 and mode stall a crendenza at Council prefunction area	·				-	
		ļ	<u> </u>		<del> </del>	
in & install additional shelving unit above nza @ room 360	\$935	Millwork Hold:	S <sub>I</sub>		1	
door hardware for doors supplied by Fetzer (	3	Milwork Hold	5	1	1	
al chambers for labor increase starting on July 1, 2002.	\$ 4,000		<del> </del>	<del> </del>		
ated to be 2000 hours @ \$ 2.00/hr		,	<b> </b>	ļ	<del> </del>	
for per diem increase starting on July 1, 2002. aled to be 12 weeks	\$ 1,260	'}	1		1	
tments to Millwork on sunscreen	\$ 6,000		ļ			
c laminated panels at top of upper cabinets.			ļ		-	
sh and install window sills at 3rd Floor, Grid Li			ļ		_	
is provides the City Clerks' office the ability to be window sill as a countertop.	30,000					
ils provides the City Clerks' office the ability to be window sill as a countertop. Time premium for weekend and evening work, quired to coordinate the council chambers wo actor is also paying for their share of overtime	\$ 175			ļ	-	
ils provides the City Clerks' office the ability to be window sill as a counteriop. Ime premium for weekend and evening work, juired to coordinate the council chambers work actor is also paying for their share of overtime of the counter of the counter share of overtime of the counter				<u> </u>		
is provides the City Clerks' office the ability to be window sill as a countertop. time premium for weakend and avening work, juried to coordinate the council chambers wo actor is also paying for their share of overtime lassite laminate door at Room 215. 21 shelving units at Room 369.						
is provides the City Clerks' office the ability to be window sill as a countertop. Imp premium for weekerd and avening work, juried to coordinate the council chambers wo actor is also paying for their share of overtime objects in the counter of the counter of the objects of the counter of the counter of the 21 shalving units at Room 390, mounting board for plan holders olded of Self Help Desk.	1		_L* •••	City Hall Technology (#8142	4_	
- "	and Install window sals at 3rd Floor, Glid Lib provides the City Clerks' office the ability to window sill as a sountertop. p premium for weakend and evening work, red to coordinate the council chambers wor or is also paying for their share of overtime stic laminate door at Room 215. shelving unds at Room 300. unifice board for plan holders	and instalt window sits at 3rd Floor, Grid Line provides the Cty Clerks office the ability to windows 81 as a Counterfloor.  In premium for weekend and evening work, ed to coordinate the councit chambers work, or is also paying for their share of overtime site laminate door at Room 215.  S 172 shelving units at Room 390.  \$1.377 uniting board for plan hoters \$5.572 et of Set Help Cesk.	and install window sits at 3rd Ficor. Grid Line \$ 4,530 provides the City Clerks' office the ability to window sill as a counterion. Be premium for weekend and avening work, red to coordinate the council chambers work to is also paying for their share of overtime sits is also paying for their share of overtime 30,000 sits laminate door at Room 215. \$ 175 shelving units at Room 390. \$ 1,870 uniting board for plan holders \$ 5.75 to 10 Set Hale Desk. \$ 105 eccton screen shroud per RFI 734A dated 2.	and Install window sits at 3rd Ploor, Grid Line provides the City Clerks' office the ability to window sill as a counterior.  p premium for weekerd and evening work, red to coordinate the council chambers work, to is also paying for their share of overtime sits laminate door at Room 215.  \$ 175 \$helving units at Room 380.  \$ 1,870 uniting board for plan holders \$ 5.55  to 6 Set Hallo Desk.  \$ 880 \$ 880	and Instalt window sils at 3rd Floor, Grid Line provides the City Clerks office the ability to window sills as counterion. premium for weekend and evening work, ed to coordinate the councit chambers work, or is also paying for their share of overtime 30,000 site igminate door at Room 215. \$ 175 shalving units at Room 389. \$ 1,870 unifine board for glain bodders \$ 5 75 of Self help Desk. \$ 165  City Hall Technology (#8142)	and Install window sits at 3rd Floor, Grid Line \$ 4,590 provides the CRy Clerks' office the ability to window sits a 5rd Floor, Grid Line \$ 4,590 provides the CRy Clerks' office the ability to window sits a 5 counterton. The control of the contro

		HOLDS OR UNB	OUGHTS	OTHER CIP PRO	JECT8	CONTI	NGENCY
Change Order	D		Description	amount	C1P project description	_	iount
	Description  Refinish the panels in the Council Chambers gallery	Amount	Detemption	amount	CIP project description	111	ioun;
	due to damage caused by other trade (this will be backcharged to responsible contractor.)					\$	520
	Up Grade Council Chamber roof membrane to 4-pty					5	1,670
200-031	plus cap sheet. Miscellaneous waterproofing patching.			ļ <u>.</u>		\$	8,02
200-032	Modify pavers to fit at 2nd Floor.					Š	3,900
3200-033 3200-034	Waterproofing repair. Repair leaky drain and replace and re-roof area of					\$	5,500
3200-035	repair  Credit for backcharge items: Rotunda scaffolding,			ļ		<u> </u>	846
	trash boxes, removal/reinstall light flutures, and clearl/repaint window frames.		. <u> </u>			\$	(4,596
3200-036	Labor rate increase of \$2.00 per hour for September. Per diem increase for September.			ļ		\$	2,770
200-037	Per clem increase for September.					*	30
220-001	FERMA additional labor time and materials - fence parking lot					\$	3,03
2220-002	minor plan revisions - temporary parking lot	ļ				\$	2,00
2220-003	Excavation overtime					5	85
2220-004	Garage sumps excavation - to provide well in fleu of pumps, this change order is combined with 15900-01	\$ 11,000		}			
2220-005	below as a value engineering revision. drain rock at mat slab					5	9,35
2220-006	Wintenzation - to provide site access and meet the Storm Water Pollution requirements	\$ 26,805	Gen. Conditions				
2220-007	Shoring and Garage Drainage - provide larger electrical power generator due to use of larger pumps than anticipated, Reiscate shoring for garage ramp due to architectural revisions (total = \$56,000).	\$ 63,112	Stework			s	22,888
2220-008	Additional work at ramp Total approved by Council is \$227,315. (Refer to Conco PCO-037)					\$	35,000
2220-009						l	
	Delete ramp wall vertical storm drainage system pipe from contract. Contractor has demobilized and work could not proceed because of ramp delays. The ramp issues have been resolved and a remobilization cost would be incurred if Ferma comes back. This work has been regulated with Division Two who is on ste and can actually do this for much less for the sterman of the process of the process of the process of the process of the process of the process of the process of the process of the process of the process of the process of the process of the process of process of the process of process of the process of process of the process of process (11.000)		:				
	FIGUERAS SEATING			<u> </u>			
1	Additional cost to provide union labor for installation	\$4,690	FF& E holds				
<u>_</u>	of seals in the Council Chambers Changes to seats @ council chambers	\$ 1,075	<del> </del>				
3	Additional trip for layout and location of Power/Data						
4	Additional shipment trip, due to delay from ACCO	\$ 450					
	(cost will be backcharged to ACCO)	700					
5		139.		<b> </b>		\$	1,60
5	council chambers	N.Y.				\$	1,60
	council chambers HELWIG PLUMBING	TAY.		\$ 36.207	Pord Reposition (#8141)	\$	1,60
15400-003 15400-004	council chambers	\$ (38,984)		\$ 36,207	Pand Renovation (#8141)	5	1,60
15400-003 15400-004	council chambers HELWIG PLUMBING Fountain Equipment Room Garage Orainage elimination - credit		Site landscaping	\$ 38,207	Pand Renovation (#8141)	\$	1,50
15400-003 15400-004 15400-005	councel chambers  HELWIG PLUMBING Fountain Equipment Room Garage Orainage elimination - credit See Area Drain's - added more drains	\$ (38,984)	landscaping plumbing	\$ 38,207	Pend Renovation (#8141)	5	1,50
15400-003 15400-004 15400-005	council chambers HELWIG PLUMBING Fountain Equipment Room Garage Orainage elimination - credit	\$ (38,084) \$ 17,538 \$ 2,469	landscaping plumbing holds	\$ 36,207	Pend Renovation (#8141)	\$	1,50
15400-003 15400-004 15400-005 15400-006	councel chambers  HELWIG PLUMBING Fountain Equipment Room Garage Orainage elimination - credit See Area Drain's - added more drains	\$ (38,984) \$ 17,538 \$ 2,469 \$ 26,164	landscaping plumbing holds plumbing holds	\$ 38,207	Pend Renovation (#8141)	\$	1,50
5 15400-003 15400-004 15400-005 15400-006 15400-007	council chambers  HELWIG PLUMBING Fountain Equipment Room Garage Oralinage chimination - credit  See Area Drains - added more drains Equipment Drains - for airconditioning system	\$ (38,084) \$ 17,538 \$ 2,469	landscaping plumbing holds plumbing	\$ 38,207	Pand Renovation (#6141)	\$	
15400-003 15400-004 15400-005 15400-006 15400-007 15400-008 15400-009	council chambers  HELWIG PLUMBING  Fountain Equipment Room  Garage Oralingte elimination - credit  Site Area Drains - added more drains  Equipment Drains - for airconditioning system  Root overflow drains - to replace side drains  Hose bibs - additional needed for maintenance  Drinking fountain in Exercise room	\$ (38,984) \$ 17,538 \$ 2,469 \$ 26,164	landscaping plumbing holds plumbing holds plumbing	\$ 38,207	Pend Renovation (#8141)	\$	2,04
15400-003 15400-004 15400-005 15400-006 15400-007 15400-008 15400-009 15400-010	council chambers  HELWIG PLUMBING  Foundain Equipment Room  Garage Orainsge elimination - credit  Sée Area Drains - added more disins  Equipment Drains - for airconditioning system  Roof overflow drains - to replace side drains  Hose bibs - additional needed for maintenance  Drinking foundain in Exercise room  Carlé sink - not included in original design	\$ (38,984) \$ 17,538 \$ 2,469 \$ 26,164	landscaping plumbing holds plumbing holds plumbing	\$ 38,207	Pand Renovation (#8141)	\$	2,04
15400-003 15400-004 15400-005 15400-005 15400-007 15400-009 15400-010 15400-011 15400-011	council chambers  HELWIG PLUMBING  Foundain Equipment Room  Garage Orainsge elimination - credit  See Area Drains - added more disins  Equipment Drains - for airconditioning system  Roof overflow drains - to replace side drains  Hose bibs - additional needed for maintenance Drinking foundain in Exercise room  Caffe sink - not included in original design  Breakroom sink - not included in original design  Breakroom sink - not included in original design	\$ (38,984) \$ 17,538 \$ 2,469 \$ 26,164	landscaping plumbing holds plumbing holds plumbing	\$ 36,207	Pand Renovation (#8141)	\$	2,04 7,64 7,84 1,58
15400-003 15400-004 15400-005 15400-005 15400-007 15400-008 15400-009 15400-010 15400-011 15400-012 15400-013	council chambers  HELWIG PLUMBING  Foundain Equipment Room  Garage Orainsge elimination - credit  See Area Drains - added more disins  Equipment Drains - for airconditioning system  Roof overflow drains - to replace side drains  Hose bibs - additional needed for maintenance Drinking foundain in Exercise room  Caffe sink - not included in original design  Breakroom sink - not included in original design  Council Sreakroom wet bar - not included in original	\$ (38,984) \$ 17,538 \$ 2,469 \$ 26,164	landscaping plumbing holds plumbing holds plumbing	\$ 38,207	Pand Renovation (#8141)	\$ \$ \$ \$ \$	2,04 7,64 7,84 1,58
15400-003 15400-004 15400-005 15400-006 15400-007 15400-008 15400-010 15400-011 15400-013 15400-013 15400-013	council chambers  HELWIG PLUMBING  Fountain Equipment Room  Garage Oralingte elimination - credit  Site Area Drains - added more drains  Equipment Drains - for airconditioning system  Root overflow drains - to replace side drains  Hose bibs - additional needed for maintenance  Drinking fountain in Exercise room  Carle sink - not included in original design  Recessed Drinking Fountain on 1st floor  Council Breakroom with air - not included in original  design.  Additional Water closesturinais - size of public  restrooms increaged	\$ (38,984) \$ 17,538 \$ 2,469 \$ 26,164	landscaping plumbing holds plumbing holds plumbing	\$ 38,207	Pand Renovation (#8141)	\$ \$ \$ \$ \$	2,04 7,84 7,84 1,58 1,52
15400-003 15400-004 15400-005 15400-006 15400-007 15400-008 15400-010 15400-013 15400-013 15400-014 15400-014 15400-014	council chambers  HELWIG PLUMBING  Fountain Equipment Room  Garage Drainage elimination - credit  Sée Area Drains - added more drains  Equipment Drains - for airconditioning system  Root overflow drains - to replace side drains  Hose bibs - additional needed for maintenance Drinking fountain in Exercise room  Carle sink - not included in original design  Recessed Drinking Fountain on 1st floor  Council Streakroom wet bar - not included in original design  Additional Water closesturinals - size of public  restrooms increased  Jantorial Sinks - not included in original design  Automatic Pumbing fictures - added to conserve	\$ (38,984) \$ 17,538 \$ 2,469 \$ 26,164	landscaping plumbing holds plumbing holds plumbing	\$ 38,207	Pand Renovation (#8141)	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	2,04 7,64 7,64 1,58 1,52 5,66 4,66
15400.003 15400.003 15400.005 15400.005 15400.007 15400.007 15400.003 15400.001 15400.013 15400.013 15400.013 15400.013 15400.014 15400.015 15400.018	council chambers  HELWIG PLUMBING  Garage Orainage elimination - credit  Sãe Area Drainage elimination - credit  Roof ovariflow drainage - for airconditioning system  Roof ovariflow drainage - for airconditioning system  Roof ovariflow drainage - for airconditioning system  Roof ovariflow drainage - for airconditioning fountian in Exercise room  Carlé sink - not included in original design  Breakroom sink - not included in original design  Roof ovariflow drainage - for included in original design  Automatic Plumbing Fountian on 1st foor  Council Breakroom wet bar - not included in original design  Automatic Plumbing Butures - added to conserve water use  Install 3/4* domestic water line (330 LF fotal) to dinnking fountain and to hose bit at rash enclosure.	\$ (38,984) \$ 17,538 \$ 2,469 \$ 26,164	landscaping plumbing holds plumbing holds plumbing holds	\$ 30,207	Pand Removation (#6141)	\$ \$ \$ \$ \$	2,04 7,84 7,84 1,58 1,52
15400-003 15400-004 15400-005 15400-005 15400-007 15400-007 15400-001 15400-013 15400-013 15400-013 15400-013 15400-014 15400-015 15400-016	council chambers  HELWIG PLUMBING  Fountain Equipment Room  Garage Drainseq elimination - credit  Sée Area Drains - added more drains  Equipment Drains - for airconditioning system  Root overflow drains - to replace side drains  Hose bibs - additional needed for maintenance Drinking fountain in Exercise room  Carls sink - not included in original design  Breakroom sink - not included in original design  Recessed Drinking Fountain on 1st floor  Council Breakroom wet bar - not included in original design  Automatic plumbing fidures - added to conserve water use  Install 3/4* domestic water line (330 LF total) to drinking fountain and to hose bib at trash enclosure.  Routed along garage ceiling (96 LF) to trench on-  ste (234 LF)  Funnish and Install a 4* pressure reducing valve with	\$ (38,964) \$ 17,536 \$ 2,469 \$ 26,164 \$ 9,635	landscaping, plumbing holds plumbing plumbing plumbing plumbing plumbing plumbing holds	\$ 38,207	Pand Renovation (#8141)	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	2,04 7,64 7,84 1,58 1,52 5,66
15400-003 15400-004 15400-005 15400-005 15400-007 15400-008 15400-019 15400-011 15400-013 15400-014 15400-015 15400-017	council chambers  HELWIG PLUMBING  Garage Drainseq elimination - credit  Sée Area Drainse e elimination - credit  Sée Area Drainse e elimination - credit  Sée Area Drainse - for airconditioning system  Roof overflow drains - to replace side drains  Hose bibs - additional needed for maintenance  Drinking fountain in Exercise coom  Carls sink - not included in original design  Breaknoom sink - not included in original design  Recessed Drinking Fountain on 1st floor  Council Brasknoom web bar - not included in original design  Additional Water close/burinals - size of public restrooms increased  Jantorial Sinks - not included in original design  Automatic plumbing flutures - added to conserve water use.  Install 3/4" domestic water line (330 LF total) to drinking fountain and to hose bib at trast enclosure. Rouded along garage ceiling (96 LF) to tranch on-  site (234 LF).  Furnish and Install a 4" pressure reducing valve with a 2" bypass station for domestic water service to building	\$ (38,984) \$ 17,535 \$ 2,469 \$ 26,164 \$ 9,635 \$ \$5,024	landscaping, plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds	\$ 38,207	Pand Renovation (#8141)	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	2,04 7,64 7,84 1,58 1,52 5,66
15400-003 15400-004 15400-005 15400-005 15400-007 15400-008 15400-010 15400-011 15400-012 15400-014 15400-017 15400-017	council chambers  HELWIG PLUMBING  Garage Drainseq elimination - credit  Sée Area Drainse e elimination - credit  Sée Area Drainse e elimination - credit  Sée Area Drainse e elimination - credit  Sée Area Drainse - for airconditioning system  Roof overflow drains - to replace side drains  Hose bibs - additional needed for maintenance Drinking fountain in Exercise room  Carls sink - not included in original design  Recessed Drinking Fountain on 1st Foor  Council Brainseroom web bar - not included in original design  Recessed Drinking Fountain on 1st Foor  Council Brainseroom web bar - not included in original design  Jantorial Sinks - not included in original design  Automatic plumbing lidures - added to conserve water use  Install 344* domestic water line (330 LF total) to drinking fountain and to hose bib at trash enclosure. Routed along garage ceiling (96 LF) to trench on-  seg (234 LF)  Furnish and install a 4* pressure reducing valve with a 2* bypass station for domestic water service to building.	\$ (38,984) \$ 17,538 \$ 2,469 \$ 26,164 \$ 9,635 \$5,024 \$8,437	Igndscaping, plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds Plumbing holds Plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds	\$ 38,207	Pand Renovation (#8141)	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	2,04 7,64 7,84 1,58 1,52 5,66
15409-003 15409-004 15409-005 15409-005 15409-007 15409-007 15409-011 15409-011 15409-013 15409-013 15409-014 15409-015 15409-017 15409-017 15409-017	council chambers  HELWIG PLUMBING  Garage Drainseq elimination - credit  Sée Area Drains - added more drains  Equipment Drains - for airconditioning system  Roof overflow drains - to replace side drains  Hose bibs - additional needed for maintenance Drinking fountial in Exercise room  Café sink - not included in original design  Breakroom sink - not included in original design  Recessed Drinking Fountain on 1st froor  Council Breakroom web bar - not included in original design  Recessed Drinking Fountain on 1st froor  Council Breakroom web bar - not included in original design  Additional Water closeburinals - size of public restrooms increased  Jantorial Sinks - not included in original design  Automatic plumbing fluures - added to conserve water use  Install 3/4* domestic water line (330 LF fotal) to dinnking fountain and to hose bit at trash enclosure.  Routed along garage ceiling (96 LF) to trench or- sto (234 LF)  Furnish and Install a 4* pressure reducing valve with a 2* organs and install a 4* pressure reducing valve with a 2* organs and install a 4* pressure reducing valve with a 2* organs and install a 4* pressure reducing valve with a 2* organs and install a 4* pressure reducing valve with a 2* organs and install a 4* pressure reducing valve with a 2* organs and install a 4* pressure reducing valve with a 2* organs and install a 4* pressure reducing valve with a 2* organs and install a 4* pressure reducing valve with a 2* organs and install a 4* pressure reducing valve with a 2* organs and install a 4* pressure reducing valve with a 2* organs and install a 4* pressure reducing valve with a 2* organs and install a 4* pressure reducing valve with a 2* organs and and a 2* organs and a 2* or	\$ (38,984) \$ 17,538 \$ 2,469 \$ 26,164 \$ 9,635 \$5,024 \$8,437 \$526 \$2,240	landsealing, plumbing holds plumbing holds plumbing holds plumbing holds.  Plumbing holds plumbing holds.  Plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds.	\$ 38,207	Pand Renovation (#8141)	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	2,04 7,64 7,84 1,58 1,52 5,66
15400-003 15400-004 15400-005 15400-005 15400-007 15400-008 15400-010 15400-011 15400-012 15400-014 15400-017 15400-017	council chambers  HELWIG PLUMBING  Foundain Equipment Room  Garage Orainsge elimination - credit  See Area Drains - added more drains  Equipment Drains - for airconditioning system  Root overflow drains - to replace side drains  Hose bibs - additional needed for maintenance  Drinking foundain in Exercise room  Carlé sink - not included in original design  Breakroom sink - not included in original design  Breakroom sink - not included in original design  Recessed Drinking Foundain on 1st floor  Council Breakroom wet bar - not included in original  design  Additional Water close/urinals - size of public  restrooms increased  Jantorial Sinks - not included in original design  Automatic plumbing librares - added to conserve  water use  Install 3/4* domestic water line (330 LF total) to  drinking foundain and to hose bith at trash enclosure.  Routed along garage celling (96 LF) to trench on-  sto (234 LF)  Furnish and Install a 4* pressure reducing valve with  a 2* orypass station for domestic water service to  building  a 2* orypass station for domestic water service to  building  a 2* orypass station for domestic water service to  building  a 2* orypass station for domestic water service to  building  a 2* orypass station for domestic water service to  building  a 2* orypass station for domestic water service to  building  a 2* orypass station for domestic water service to  building  a 2* orypass station for domestic water service to  building  a 2* orypass station for domestic water service to  building  president in the design of the pressure reducing valve with a 2* orypass station for domestic water service to  building  president in the design of the pressure reducing valve with a 2* orypass station for domestic water service to  building  president in the design of the pressure reducing valve with a 2* orypass station for domestic water service to  pressure a design of the pressure reducing valve with a 2* orypass station of the pressure reducing valve with a 2* orypass station of the pressure reducing valve	\$ (38,984) \$ 17,538 \$ 2,469 \$ 26,164 \$ 9,635 \$5,024 \$8,437	landsearing, plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds	\$ 38,207	Pand Renovation (#8141)	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	2,04 7,64 7,84 1,58 1,52 5,66
15400-003 15400-005 15400-005 15400-005 15400-007 15400-007 15400-010 15400-011 15400-011 15400-013 15400-013 15400-014 15400-015 15400-017	council chambers  HELWIG PLUMBING  Garage Drainseq elimination - credit  Sée Area Drains - added more drains  Equipment Drains - for airconditioning system  Roof overflow drains - to replace side drains  Hose bibs - additional needed for maintenance Drinking fountial in Exercise room  Café sink - not included in original design  Breakroom sink - not included in original design  Recessed Drinking Fountain on 1st froor  Council Breakroom web bar - not included in original design  Recessed Drinking Fountain on 1st froor  Council Breakroom web bar - not included in original design  Additional Water closeburinals - size of public restrooms increased  Jantorial Sinks - not included in original design  Automatic plumbing fluures - added to conserve water use  Install 3/4* domestic water line (330 LF fotal) to dinnking fountain and to hose bit at trash enclosure.  Routed along garage ceiling (96 LF) to trench or- sto (234 LF)  Furnish and Install a 4* pressure reducing valve with a 2* organs and install a 4* pressure reducing valve with a 2* organs and install a 4* pressure reducing valve with a 2* organs and install a 4* pressure reducing valve with a 2* organs and install a 4* pressure reducing valve with a 2* organs and install a 4* pressure reducing valve with a 2* organs and install a 4* pressure reducing valve with a 2* organs and install a 4* pressure reducing valve with a 2* organs and install a 4* pressure reducing valve with a 2* organs and install a 4* pressure reducing valve with a 2* organs and install a 4* pressure reducing valve with a 2* organs and install a 4* pressure reducing valve with a 2* organs and install a 4* pressure reducing valve with a 2* organs and and a 2* organs and a 2* or	\$ (38,984) \$ 17,538 \$ 2,469 \$ 26,164 \$ 9,635 \$5,024 \$8,437 \$526 \$2,240	landsearing, plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds	\$ 38,207	Pand Renovation (#8141)	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	2,04 7,64 7,84 1,58 1,52 5,66
15400-003 15400-004 15400-005 15400-005 15400-007 15400-007 15400-001 15400-013 15400-013 15400-014 15400-015 15400-017 15400-017 15400-018 15400-018 15400-018	council chambers  HELWIG PLUMBING  Gerage Orainage elimination - credit  See Area Drains - added more distins  Equipment Drains - for airconditioning system  Roof ovariflow drains - to replace side drains  Higse bibs - additional needed for maintenance  Drinking foundan in Exercise room  Carls sink - not included in original design  Breakroom sink - not included in original design  Breakroom sink - not included in original design  Recessed Drinking Foundain on 1st floor  Council Breakroom wet bar - not included in original  destinance of the second or second or second in control or council Breakroom wet bar - not included in original  destinance or second or	\$ (36,964) \$ 17,538 \$ 2,469 \$ 26,164 \$ 9,635 \$5,024 \$8,437 \$528 \$2,248 \$548	landsearing, plumbing holds plumbing holds plumbing holds.  Plumbing holds plumbi	\$ 38.207	Pond Renovation (#8141)	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	2,04 7,64 7,84 1,58 1,52 5,66
15400-003 15400-004 15400-005 15400-005 15400-005 15400-008 15400-009 15400-010 15400-011 15400-013 15400-013 15400-014 15400-015 15400-017 15400-018 15400-018 15400-018 15400-018 15400-018	council chambers  HELWIG PLUMBING  Garage Drainseq elimination - credit  Sée Area Drainse elimination - credit  Sée Area Drainse elimination - credit  Sée Area Drainse elimination - credit  Sée Area Drainse elimination - credit  Sée Area Drainse - for aircondritioning system  Roof overflow drains - to replace side drains  Hose bibs - additional needed for maintenance  Drinking fountain in Exercise room  Carlé sink - not included in original design  Recessed Drinking Fountain on 1st Floor  Council Brainse on the council original design  Recessed Drinking Fountain on 1st Floor  Council Brainse on the council original design  Recessed Drinking Fountain on 1st Floor  Council Brainse on the council original design  Automatic plumbing flutures - added to conserve water use.  Install 344* domestic water line (330 LF total) to drinking fountain and to hose bit at trash enclosure.  Routed along garage ceiling (96 LF) to trench on-  seg (234 LF)  Furnish and Install a 4* pressure reducing valve with a 2* bypass station for domestic water service to building.  Pipe relocation in Council Chambers - for HVAC system  Reppe water line @ lavatory waits due to conflicts wath stantons supports.  Furnish & Install cold water line extension @ trash enclosure.  Furnish & Install two grates for elevator sump	\$ (38,984) \$ 17,538 \$ 2,469 \$ 26,164 \$ 9,635 \$ 5,024 \$ \$3,437 \$ \$528 \$ \$2,249 \$ \$426	landsearing, plumbing holds plumbing holds plumbing holds plumbing holds.  Plumbing holds plumbing holds plumbing holds.  Plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing plumbing holds plumbing holds plumbing holds plumbing holds plumbing plumbing holds p	\$ 30,207	Pond Removation (#8141)	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	2,04 7,64 7,84 1,58 1,52 5,66
15400-003 15400-004 15400-005 15400-005 15400-005 15400-007 15400-003 15400-013 15400-013 15400-014 15400-015 15400-017 15400-017 15400-019 15400-019 15400-019 15400-019 15400-019 15400-020 15400-020 15400-021	council chambers  HELWIG PLUMBING  Gerage Orainage elimination - credit  See Area Drains - added more disins  Equipment Drains - for airconditioning system  Roof ovariflow drains - to replace side drains  Hose bibs - additional needed for maintenance  Drinking foundar in Exercise room  Carls sink - not included in original design  Breakroom sink - not included in original design  Breakroom sink - not included in original design  Breakroom with a not included in original design  Additional Water close/furnials - size of public  restrooms lineraged  Jantonial Sinks - not included in original design  Automatic plumbing flutures - added to conserve  water use.  Install 3/4* domestic water line (330 LF fota) to  dinnking foundar and to hose bib at trast enclosure.  Routed along garage ceiling (96 LF) to trench on-  sets (234 LF).  Furnish and Install a 4* pressure reducing valve with  a 2* brybas station for domestic water service to  building.  Purplish a Install cold water line extension @ trash  enclosure.  Furnish & Install cold water line extension @ trash  enclosure.  Furnish & Install cold water line extension @ trash  enclosure.  Furnish & Install cold water line extension @ trash  enclosure.  Furnish & Install cold water line extension @ trash  enclosure.  Furnish & Install cold water line extension @ trash  enclosure.  Furnish & Install cold water line extension @ trash  enclosure.  Furnish & Install cold water line extension with the plumbine & eliminated water beater at first floor.  Revisions resulted in cost savings.  Project Labor hourly rale increase from July 30,	\$ (38,984) \$ 17,535 \$ 2,469 \$ 26,164 \$ 9,635 \$\$5,024 \$\$5,437 \$\$526 \$2,249 \$\$48 \$\$426 (\$1,334)	landseacing, plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds credit	\$ 38.207	Pond Renovation (#8141)	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	2,04 7,64 7,84 1,58 1,52 5,66
15400-003 15400-005 15400-005 15400-005 15400-005 15400-007 15400-003 15400-011 15400-013 15400-013 15400-014 15400-017 15400-017 15400-019 15400-019 15400-019 15400-021 15400-021 15400-021 15400-021 15400-021	council chambers  HELWIG PLUMBING  Garage Orsinage elimination - credit  Site Area Drains - added more drains  Equipment Drains - for airconditioning system  Roof ovariflow drains - to replace side drains  Hose bibs - additional needed for maintenance  Drinking fountian in Exercise room  Caffe sink - not included in original design  Breakroom sink - on included in original design  Recessed Drinking Fountian on 1st foor  Council Breakroom web bar - not included in original design  Recessed Drinking Fountian on 1st foor  Council Breakroom web bar - not included in original design  Recessed Drinking Fountian on 1st foor  Council Breakroom web bar - not included in original design  Automatic plumbing fibures - added to conserve  water use  Install 3/4* domestic water line (330 LF fotal) to  drainking fountian and to hose bib at trash enclosure.  Routed along garage calling (96 LF) to trench on- ster (234 LF)  Furnish and Install a 4* pressure reducing valve with a 2* bypass station for domestic water service to  building  Pipe relocation in Council Chambers - for HVAC  system  Reppe water line @ lavatory walls due to conflicts with stantion supports  Furnish & Install cold water line extension @ trash  enclosure.  Furnish & Install in wo grates for elevator sump  Increased water heater size at 4th floor including  plumbine & eliminated water heater at first floor.  Furnish & Install into water line extension @ trash  enclosure.  Furnish and install flush mount (8) wall hydrants  Project Labor hourly rale increase from July 30,  2001 through end of project.  Rembusement (credit) for water damaget to the place	\$ (38,984) \$ 17,535 \$ 2,469 \$ 26,164 \$ 9,635 \$\$5,024 \$\$8,437 \$528 \$2,249 \$548 \$426 (\$1,334)	landsealing, plumbing holds plumbing holds plumbing holds plumbing holds.  Plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds / credit plumbing holds / credit plumbing holds / credit plumbing holds / credit plumbing holds / credit plumbing holds / credit plumbing holds / credit plumbing holds / credit / plumbing holds / credit / plumbing holds / credit / plumbing holds / credit / plumbing holds / credit / plumbing holds / credit / plumbing holds / credit / plumbing holds / credit / plumbing holds / credit	\$ 38.207	Pend Renovation (#8141)	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	2,04 7,64 7,84 1,58 1,52 5,66
15400-003 15400-005 15400-005 15400-005 15400-007 15400-007 15400-001 15400-011 15400-012 15400-013 15400-013 15400-013 15400-014 15400-015 15400-017 15400-017 15400-019 15400-020 15400-020 15400-020 15400-020 15400-020	council chambers  HELWIG PLUMBING  Gerage Orainsge elemination - credit  See Area Drains - added more disins  Equipment Drains - for airconditioning system  Roof ovariflow drains - to replace side drains  Hose bibs - additional needed for maintenance  Drinking fountain in Exercise room  Carlé sink - not included in original design  Breakroom sink - not included in original design  Breakroom sink - not included in original design  Breakroom sink - not included in original design  Recessed Drinking Fountain on 1st floor  Council Breakroom wet bar - not included in original  design  Additional Water close/furinals - size of public  restrooms lincreaged  Jantonial Sinks - not included in original design  Automatic plumbling fidures - added to conserve  water use.  Install 3/4* domestic water line (330 LF fotal) to  dinnking fountain and to hose bib at trast enclosure.  Routed along garage ceiling (96 LF) to trench on-  sets (234 LF).  Furnish and Install a 4* pressure reducing valve with  a 2* brybase station for domestic water service to  building.  Purple selection in Council Chambers - for HVAC  system  Europe water line @ lavatory walls due to conflicts  with stanton supports.  Furnish & Install cold water line extension @ trash  enclosure.  Furnish & Install cold water line extension @ trash  enclosure.  Furnish & Install invo grates for elevator sump  lincreased water heater size at 4th floor including  plumbine & eleminated water heater at first floor.  Revisions resulted in cost saviross.  Project Labor hourly rate increase from July 30,  2001 through end of project.	\$ (38,984) \$ 17,538 \$ 2,469 \$ 26,164 \$ 9,635 \$5,024 \$8,437 \$526 \$2,249 \$548 \$426 (\$1,334) \$1,114 \$ 13,160	landsealing, plumbing holds plumbing holds plumbing holds plumbing holds.  Plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds / credit plumbing holds / credit plumbing holds / credit plumbing holds / credit plumbing holds / credit plumbing holds / credit plumbing holds / credit plumbing holds / credit / plumbing holds / credit / plumbing holds / credit / plumbing holds / credit / plumbing holds / credit / plumbing holds / credit / plumbing holds / credit / plumbing holds / credit / plumbing holds / credit	\$ 38.207	Pond Renovation (#8141)	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	2,04 7,64 7,84 1,58 1,52 5,66
15400-003 15400-004 15400-005 15400-005 15400-005 15400-003 15400-010 15400-011 15400-013 15400-013 15400-013 15400-014 15400-015 15400-018 15400-018 15400-019 15400-020 15400-021 15400-022 15400-023 15400-023	council chambers  HELWIG PLUMBING  Gerage Orainsge elemination - credit  See Area Drains - added more disins  Equipment Drains - for airconditioning system  Roof overflow drains - to replace side drains  Hose bibs - additional needed for maintenance  Drinking foundar in Exercise room  Carlé sink - not included in original design  Breakroom sink - not included in original design  Breakroom sink - not included in original design  Breakroom sink - not included in original design  Recessed Drinking Foundarion in st floor  Council Breakroom wet bar - not included in original  design  Additional Water close/furinals - size of public  restrooms lincreased  Janitorial Sinks - not included in original design  Automatic plumbing flutions - added to conserve  water use  Install 3/4* domestic water line (330 LF fotal) to  dinnking foundari and to hose bib at trash enclosure.  Routed along garage ceiling (96 LF) to trench on-  set (234 LF)  Furnish and install a 4* pressure reducing valve with  a 2* brybass station for domestic water service to  building  Proper closed on in Council Chambers - for HVAC  system  Furnish & install tools water line extension @ trash  enclosure.  Furnish install two grates for elevator sump  increased water heater size at 4th floor including  plumbine & eleminated water heater at first floor.  Revisions cesulted in cost savings.  Furnish and install flush mount (8) wall hydrants  Project Labor hourly rate increase from July 30,  2001 through end of protect  Reminusement (credit) for water damaged to  drywall and insulation due to test plug left in place	\$ (38,984) \$ 17,538 \$ 2,469 \$ 26,164 \$ 9,635 \$5,024 \$8,437 \$526 \$2,249 \$548 \$426 (\$1,334) \$1,114 \$ 13,160	landsearing, plumbing holds plumbing holds plumbing holds.  Plumbing holds plumbing holds.  Plumbing holds.  Plumbing holds.  Plumbing holds you can be plumbing holds.  Plumbing holds / credit plumbing holds / credit plumbing holds / credit plumbing holds.	\$ 38.207	Pond Renovation (#8141)	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	2,04 7,64 7,84 1,58 1,52 5,66
15400-003 15400-004 15400-005 15400-005 15400-005 15400-009 15400-019 15400-013 15400-013 15400-013 15400-015 15400-015 15400-015 15400-016 15400-016 15400-017 15400-018 15400-020 15400-020 15400-021 15400-023 15400-023 15400-023 15400-024 15400-025 15400-025 15400-026	council chambers  HELWIG PLUMBING  Garage Orainsge elemination - credit  See Area Drains - added more distins  Equipment Drains - for airconditioning system  Roof overflow diams - to replace side drains  Hose bibs - additional needed for maintenance  Drinking fountain in Exercise room  Additional register for included in original design  Breakroom sink - not included in original design  Breakroom sink - not included in original design  Breakroom sink - not included in original design  Breakroom sinks - not included in original design  Recessed Drinking Fountain on 1st floor  Council Breakroom wet bar - not included in original  design  Additional Water close/furinals - size of public  restrooms lincreased  Janatorial Sinks - not included in original design  Automatic plumbing fibrures - added to conserve  water use  Install 344* domestic water line (330 LF fotal) to  dinnking fountain and to hose bib at trash enclosure.  Routed along garage ceiling (96 LF) to trench on-  safe (234 LF).  Furnish and Install a 4* pressure reducing valve with  a 2* brypass station for domestic water service to  building  a 2* brypass station for domestic water service to  building  a 2* brypass station for domestic water service to  building  a 2* brypass station for domestic water service to  building  principal in stall cold water fine extension @ trash  enclosure  Furnish & install two grates for elevator sump  Increased water heater size at 4th floor including plumbine & eliminated water heater at first floor.  Revisions cesulted in cost saviross.  Project Labor hourly rate increase from July 30,  2001 through end of protect  Rembureament (credit for water damaged to  drywall and install flosh mount hydrant  Provice and Install (8) flush mount hydrant	\$ (38,984) \$ 17,538 \$ 2,469 \$ 26,164 \$ 9,635 \$5,024 \$8,437 \$5,26 \$2,249 \$426 (\$1,334) \$1,114 \$ 13,160 \$ (10,396	landsearing, plumbing holds plumbing	\$ 38.207	Pond Renovation (#8141)	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	2,04 7,64 7,84 1,58 1,52 5,66
15400-003 15400-004 15400-005 15400-005 15400-005 15400-009 15400-019 15400-013 15400-013 15400-013 15400-013 15400-013 15400-013 15400-013 15400-013 15400-013 15400-013 15400-013 15400-013 15400-013 15400-013 15400-013 15400-013 15400-013 15400-023 15400-023 15400-023 15400-023 15400-023 15400-023 15400-023	request chambers  HELWIG PLUMBING  Foundain Equipment Room  Garage Orainsge elimination - credit  See Area Drains - added more distins  Equipment Drains - for airconditioning system  Root overflow disans - to replace side drains  Hose bibs - additional needed for maintenance  Drinking foundain in Exercise room  Carlé sink - not included in original design  Breakroom sink - not included in original design  Breakroom sink - not included in original design  Breakroom sink - not included in original design  Breakroom sinks - not included in original design  Recessed Drinking Foundain on 1st floor  Council Breakroom wet bar - not included in original  design  Additional Water close/urinals - size of public  restrooms lincreased  Janitorial Sinks - not included in original design  Automatic plumbing libures - added to conserve  water use  Install 344* domestic water line (330 LF total) to  drinking foundain and to hose bib at trash enclosure.  Routed along garage ceiling (96 LT bit bir tench  service and any garage ceiling (96 LT bit bir tench  service in the service of the service to  busified  a 2* organises station for domestic water service to  busified  a 2* organises station for domestic water service to  busified  a 2* organises station for domestic water service to  busified  president in Council Chambers - for HVAC  system  Increased water heater see at 4th floor including  plumbine 8 eliminated water heater at first floor.  Revisions resulted in cost savings.  Project Labor hourly rate increase from July 30,  2001 through erd of protect  Rembursement (credit) for water damaged to  drywall and insulation due to test plug left in place inavientify. Causing flood  Throd floor RWI- relocation  Provide and install (8) flush mount hydrant  Install councal chambers roof drains	\$ (38,984) \$ 17,538 \$ 2,469 \$ 26,164 \$ 9,635 \$5,024 \$8,437 \$526 \$2,249 \$548 \$426 (\$1,334) \$ 13,160 \$ (10,396	landsearing, plumbing holds plumbing	\$ 38.207	Pond Renovation (#8141)	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	2,04 7,64 7,84 1,58 1,52 5,66
15400-003 15400-004 15400-005 15400-005 15400-005 15400-008 15400-001 15400-011 15400-013 15400-013 15400-013 15400-013 15400-013 15400-013 15400-013 15400-013 15400-013 15400-013 15400-013 15400-013 15400-013 15400-013 15400-018 15400-018 15400-021 15400-022 15400-023 15400-023 15400-023 15400-023 15400-023 15400-023 15400-023	request chambers  HELWIG PLUMBING  Foundain Equipment Room  Garage Orainsge elimination - credit  See Area Drains - added more drains  Equipment Drains - for airconditioning system  Root overflow drains - to replace side drains  Hose bibs - additional needed for maintenance  Drinking foundain in Exercise room  Carlé sink - not included in original design  Breakroom sink - not included in original design  Breakroom sink - not included in original design  Breakroom sink - not included in original design  Recessed Drinking Foundain on 1st floor  Council Breakroom wet bar - not included in original  design  Additional Water close/urinals - size of public  restrooms increased  Jantorial Sinks - not included in original  design  Additional Water close/urinals - size of public  restrooms increased  Jantorial Sinks - not included in original  design  Additional Water close/urinals - size of public  restrooms increased  Jantorial Sinks - not included in original  design  Additional Water close/urinals - size of public  restrooms increased  Jantorial Sinks - not included in original design  Additional Water close/urinals - size of public  restrooms increased  Jantorial Sinks - not included in original design  Additional Water close/urinals - size of public  restrooms increased  Jantorial Sinks - not included in original  design  and translate and water line (300 LF total) to  dinking foundain and to hose bit at trash enclosure.  Funded along garage celling (96 LF) to trench on-  ste (234 LF)  Furnish and Install cold water line adension @ trash  enclosure  Furnish & install cold water line adension @ trash  enclosure  Furnish & install cold water line adension @ trash  enclosure  Furnish & install cold water line adension @ trash  enclosure  Furnish & install cold water line adension @ trash  enclosure  Furnish & install cold water line adension @ trash  enclosure  Furnish & install cold water line (300 LF total) to  drywall and insulation due to test plug left in place  inaddiventify. Austing flood  Thrid floor RWL relo	\$ (33,984) \$ 17,538 \$ 2,469 \$ 26,164 \$ 9,635 \$5,024 \$8,437 \$528 \$2,249 \$48 \$426 (\$1,334) \$ 13,160 \$ (10,396 \$2,134 \$245	landsearing, plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds / credit plumbing holds / credit plumbing holds / plumbing holds plu	\$ 38.207	Pond Renovation (#8141)	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	2,04 7,64 7,84 1,58 1,52 5,66
15400-003 15400-004 15400-005 15400-005 15400-005 15400-009 15400-010 15400-011 15400-013 15400-013 15400-013 15400-013 15400-013 15400-014 15400-015 15400-015 15400-015 15400-015 15400-016 15400-016 15400-020 15400-020 15400-020 15400-020 15400-020 15400-021 15400-022 15400-023	council chambers  HELWIG PLUMBING  Garage Orainage elimination - credit  Sée Area Drains - added more drains  Equipment Drains - for airconditioning system  Roof ovariflow drains - to replace side drains  Hose bibs - additional needed for maintenance  Drinking fountain in Exercise room  Carle sink - not included in original design  Breakroom sink - not included in original design  Breakroom sink - not included in original design  Breakroom west bar - not included in original design  Recessed Drinking Fountain on 1st floor  Council Breakroom west bar - not included in original design  Automatic plumbing flowers - added to conserve water use  Install 3/4* domestic water line (330 LF total) to dinnking fountain and to hose bib at trash enclosure. Routed along garage ceiling (96 LF) to trench on-  stall (234 LF)  Furnish and Install a 4* pressure reducing valve with a 2* brytaes station for domestic water service to building  Pupe relocation in Council Chambers - for HVAC system  Reppe water line @ lavatory walls due to conflicts with stanton supports  Furnish & Install cold water line extension @ trash enclosure.  Purnish & Install cold water line extension @ trash enclosure.  Furnish and install flush mount (3) wall hydrants  Project Labor hourly rate increase from July 30, 2001 through end of project  Rembursement (credit) for water damaged to drywall and install flush mount (3) wall hydrants  Project Labor hourly rate increase from July 30, 2001 through end of project  Rembursement (credit) for water damaged to drywall and install flush mount (3) wall hydrants  Project Labor hourly rate increase from July 30, 2001 through end of project  Rembursement (credit) for water damaged to drywall and install flush mount (3) wall hydrants  Project Labor hourly rate increase from July 30, 2001 through end of project  Furnish and install flush mount hydrant install council chambers roof drains	\$ (33,984) \$ 17,538 \$ 2,469 \$ 26,164 \$ 9,635 \$5,024 \$8,437 \$528 \$2,248 \$426 (\$1,334) \$ 13,160 \$ (10,386 \$2,134 \$245 \$1,877	landscaping, plumbing holds plumbing holds plumbing holds plumbing holds.  Plumbing holds plumbing holds plumbing holds.  Plumbing holds plumbing holds plumbing holds plumbing holds plumbing holds.  Plumbing holds plumbing holds plumbing holds.  Plumbing holds plumbing holds plumbing holds.	\$ 38.207	Pond Renovation (#8141)	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	2,04 7,64 7,84 1,58 1,52 5,66

		HOLDS OR UNI	ROUGHTS	OTHER CIP	OTHER CIP PROJECTS		
Change Order		ſ	ſ	1	1	CONTINGENC	
,	Description	amount	Description	amount	CIP project description	amount	
5400-033	Raise floor drains on all bathrooms	\$1,739	Plumbing holds	1		i i	
5400-034	Delete EDF-1 @ room 1		Plumbing				
		\$636	holds	-			
5400-035	Service call charge for water leak in Basement (Garage). Water found was not leaking from	i					
	olumbing pipes.	639					
5400-036	Extended overhead and additional labor costs due to schedule delays	l	1	1		\$ 39,3	
5400-037	Provide two (2) grates for elevator sump pump					\$ 43	
5400-038	Provide and install flush-mount walt hydrants, six (6)			1		\$ 1,0	
5400-039	total Provide and install irrigation service, including					\$ 26,9	
5400-040	backflow preventer					\$ (6,9)	
3400-040	Contract Savings after contract closure					7.5.5.	
	INSULCRETE		ļ	_	<del></del>	<b></b>	
1	Credit for insulation not provided on roofing material	(7,780		_			
	Insulation added below at ceiling by Rollie French.	1		1		ł	
2	Remobilization due to 6 roofs not ready last fall	2,658	<del> </del>				
····	INTERFORM	<u> </u>	- <del></del>				
1	Cost for storage of furniture April through September, 2002.	1,171					
2	Patio furniture for Decks 233 & 314 and Breakroom.		1				
	Increase sales tax from 8% to 8 25%.	15,132				\$ 1	
3	ARRIGUES SERVICES TOTAL OF BUY 2076.		<del> </del>				
	ļ	<del> </del>	<del> </del>				
	IRELAND INTERIOR SYSTEMS						
	Credit for deletion of Eurospan Ceiling at 1st and 2nd	407.000	,				
2	floors Add Decoustics Ceiling at 1st and 2nd floors	(107,023	<u> </u>				
3	Add for new black duct liner at perimeters	787					
4 	Shop drawings for Eurospan Ceiling Macho shades and mini-blinds for entire building	1,368 \$30,000					
	Furnish and install Eurospan fabric on walls @	\$ 3,197					
6	council chambers, as per Detail 1/A9 20 Furnish and install Stretchwall Acoustics Panels @	\$ 31,866					
7	conference Room walls		J				
	Overtime, Premium Only, for installation of acoustical	\$ 4,160	1			1	
	ceiling as directed by City. This was necessary, in order to avoid remobilization costs to other trades	1		i			
8	due to carpet strike	45.000					
10	Window Coverings Mini-blinds, Provide special angle for acoustical ceilings at	\$ 15,000	<del>'</del>				
	perimeters of 1st. 2nd, and 3rd Floors	7,391					
11	Provide eggcrate ceiling for light coves in restrooms	3,450	Í				
12	Credit for changes form decoustic ceiling to fineline	3,430	<del>                                     </del>				
,	grid acoustical ceiling at lobby and west entrance.					i	
13	Furnish and install additional T-bar ceiling on the	(40,725	<del> </del>	-  <b>-</b>			
	fourth floor.	10,692					
14	Changes from hard ceilings to t-par ceilings in the restrooms, including credit for telecom rooms. This					ŀ	
	was a value engineering revision, which resulted in a	·	.			1	
15	net cost sayings. Install Mecho shade pockets in Rooms 210 & 362.	9,216				\$ 1,0	
16	Replace and repair damaged ceiling tile due to trade damage at 2nd & 3rd Floors.	'				\$ 1.4	
17	Replace damaged trie at Elevator Closets due to	1				\$	
40	water damage at 1st & 2nd Floors Replace and repair damaged celling tile due to trade	<del>,</del>	-			<del>-  </del>	
18	damage at 1st, 2nd, & 4th Floors.					\$ 1,1	
19	Overtime to cut sprinkler openings in tiles throughout	1				<b>S</b> :	
20	Install acoustical panel at west wall of Room 209.	<del> </del>	1			\$ 1,0	
21	Provide and install (4) manual Mechjoshades at 1st	T				\$ 1,	
	Floor Exterior Conference Room doors Upgrade to all three (3) conference room motors so	<b> </b>					
22	system can "talk" to Audio Visual System					\$ 2,	
23	Furnish and Install wall panels on west wall of Room			1		\$ 1,	
24	209 Replace ceiling tiling at various locations, due to	<del>-</del>					
	ongoing access above ceiling after move-in.					<u> </u>	
25	Provide shades for interior doors on room 167, 168					S 1.	
26	Furnish & Install sidelight blinds to room 350,			1			
	Engineering Conf	- - <del></del>	<del> </del>	<u> </u>			
		1					
1	JJR Construction  Furnish and Install 300 LF of 2 5-inch diameter PVC	-l					
•	schedule 40 main irrigation line and two each 4-inch			\$ 8	,825 Parking Circulation (#81	43)	
	PVC sleeves across new parking lot		1	٦,		1	
	Furnish and install 170 LF of 4-Inch diameter		<del> ,</del>	\$ 2	,937 CIP #8143 & Parking		
3	telephone conduit.				Circulation Project		
3	Sidewalk improvement between the City Library and Community Center	<u> </u>				\$ 12,	
4	Furnish and install PG & E transformer pad; trash					\$ 78,	
5	enclosure, and masonry brick walls Excavate and compact subgrade, place and		+				
•	compact baserock, reinforcement and concrete at		1	1		\$ 15,	
6	ramo transition Reinforce, frame, pour and finish walkway at south						
0	Reinforce, frame, pour and finish walkway at south side of garage ramp leading from existing sidewalk			-	1	\$ 13,	
	down ramp to garage.	-J	- - <del></del> -				
7	Frame reinforce, pour and finish vertical curb per detail # Sheet SK3	1	1	.[	[	\$ 18,	
8	Compact subgrade, place and compact base rock,					\$ 90,	
9	and install asphalt per detail 4 Sheet C6 01 Install trenchdrain & grate (City to furnish ) at ramp				-		
						\$ 4,	
10	Furnish materials and construct waterfall 4'x6' mockup - orkinal design	1	1	1		\$ 10,	

Change Order		HOLDS OR UNE	OUGHTS	OTHER	CIP PRO	JECTS	CONTIN	GENCY
#	Description	amount	Description	amoun	t .	CIP project description	amo	unt
11	Place concrete infill at stairs 44 and 47. Work includes preparing & clearing seel statistics para, place wekted wire mesh at landings, pour and finish 24 steps @ 34* with by 2* thick by 12* deep for stair 47 and 22 seps @42* wide by 2* thick by 12* deep. 1 tanding 75* by 3* by 5* thick, and 1 landing 7.5* by 2* by 5* thick parameters.	\$9,200	concrete holds					-
12	Increase library entrance driveway section from (6° CI II AB & 6° concrete) to (8° CI, II AB & 8° concrete with #4 reinforcement) Total cost is \$12,263			\$1,42: \$10,83		CP 4140-Milpitas Stvd US CP 4194-Calaveras Blvd US		
13	Place concrete apron and bollards for PG&E gas meter. Compact subgrade, place & compact aggregate base, and 6' thick concrete apron with #4	\$11,250	concrete holds					
14	rebar dowels at 12" on center, Furnish and install removable bumpers for trash				4 800	CIP #8143 - Parking Circulation Project		
15	enclosure Furnish and install additional concrete, reinforcing, formwork and pumping for extended landscape venear wall footing.	\$3,500	Site Concrete holds	\$	1,800	Circulation Piolect		
16	Additional asphalt paving, including demolition at west parking lot.			S	13,752	CIP #8143 - Parking & Circulation Project		
17	Core drill 8-1/4" diameter holes (165 total) at Council Chambers floor to provide air supply into Council Chambers	\$8,932	Concrete holds					
18	Parking tot striping revisions as requested by the Traffic Engineer, and additional temporary striping for interim parking lot condition.			\$	8,800	Parking Circulation (#8143)		
19	Excavation for foundations of front veneer wall foundations; trash enclosure sacking (concrete) & garage entrance; demolition of 1st waterfall mockup and construction of 2nd mockup; chipping of landing @ deck 231; grind concrete flooring at various locations in building (lotal cost is \$24,085)			\$4,28 \$19,79		CIP#8141 CIP#8026		
50	Temporary irrigation connection to irrigate street			s	006	Calaveras Blvd. Landscape (#4194)		
21	trees Furnish and install concrete wingwalls, bollards, and wall cap at trash enclosure. These dems were not included in the bit plans and are required for safety and protection.	\$5,026	Concrete holds	3	B93	(#4134)		
22	Additional excavation and installation of deeper foundations at building front jet pool (revision required due to ambiguity in plans.)	\$2,125	Concrete holds					
23 24	Furnish and construct a mockup for pond perimeter wall Additional walkway from garage ramp to Calaveras	<b>\$</b> 6,565		s	2,800	Pond Project (CIP #8141)		
25	Blvd. sidewalk to provide pathway for busstop and sidewalk on Calaveras Blvd. Credit for waterfall wall quantity and unit price (value engineering) Orig. (154 94LF @ \$900/LF) - revised		holds		(87,687	Pond Renovation (#8141)		
26 27	deskn (971F @ \$7394F) Credit for waterfall precast cap Furnish & install 14 vehicular metal bollards at	\$ 22,600	Site Holds	<u> </u>	(21,000	<u> </u>		
28	yehicular drop-off area at west parking lot.  Furnish & install concrete wall & walk for War Memorial.	\$ 10,000		-			_	
29	Furnish & install sump pits for lower pond & wall footings	\$ 20,000	1					
30 31	Furnish & install planters at trash enclosures Furnish & install perimeter cap at Amphitheater stage and front pond.	1	1					
32	Furnish & Install rebar for all site slabs Furnish & install vaults for upper and lower ponds, including footings for upper pand walls, foundation for flute player and other misc. pond structural	\$ 5,000			24,589	Pond Renovation (#8141)		
34	concrete Furnish & install concrete plynth wall at north plaza, velerans memorial wall & sidewalk, north & west plaza topping slabs and other misc. flatwork and	69,85			24,70			
35	curb concrete. Additional work at War Memorial walkway, lower pond, sump pits, planters at Trash Enclosure, and seativall.	\$ 20,000						
36	Additional Site Concrete for parking lot modifications			\$	25,000			
37	Additional funds needed due to asphalt & sidewalk quantities increase for areas which deteriorated during construction, on the west parking lot			\$	24,000	Parking Circulation (#8143)	s	29,0
38	(funding is from Civic Center - \$30,000, Parking Circulation - \$24,000 & Contingency - \$29,000)			\$	30,000	Civic Center Walkway (#8119)		
	Mauck Sheet Metal  1 Sheet Metals Changes (Including Time and Materials) for changes of sheet metal roof at Council Chambers	\$ 27,24	Site Holds					
	McGuire & Hester	-		1		1		
18	Provide pavement rehabilitation work (dig-outs) in City Hall east parking lot.			\$	10,063	L		
19	Paving-Slurry Seal east lot		,	•	23,000	Parking Circulation (#8143)	<u> </u>	
5500-001	METALAIR IRONWORKS Plan check counter supports - due to architectural revisions Stair #6 Slip-Resistant Tread. This item was not	ļ		-			\$	5,8
5500-002	included in the workscope Coring for Guardrai @ ramp. This work was not	ļ					\$	1,4
5500-005	included in the ramp work  but over budget minus value engrg deductive change	g	J	-			-  <del>-</del>	7023
	order This work includes	]	1			-		309,3
5500-006	Modified attachment of tube steel for the plan rack supports     Deletion of the star and guardrail at the garage ramp and an add for the guardrail along the side of							
	the ramp garage entrance and the handrall along the retaining wall.  3)Redesign of the supports for the 4th floor low wall.	ł						
	4)Additional of a top rail to low wall supports on the	1	1			l	ı	

		HOLDS OR UNB	STHDUC	OTHER CIP PRO	ECT8	CONT	MGENCY
Change Order	Description	amount	Description	amount	CIP project description	A	mount
	5)Credit for th detetion of the elevator tube stell above the 1st floor for Elevator #1 and #2. 6)Remove the deck and handraft posts in the way of installing roof davits and then relocate these items.						-
	7)Change post spacing of the guardra# at the retaing wall from 8'-0" - 4'-0".						
	8)Adds shim plates to low embeds to get required height on 4th floor low wall support 9)Supply and install 6 tube stell for the stone masons	\$ 2,097	Misc. fron				
500-007 500-008	Add balcany rail to 3rd floor  Expanison Joint Siza Modification from 6" to 8" joint, including time and materils (ponds of material, ponds					\$	12,97
	of tube/piper, pounds of bent plate, Hardwara, 3/4 tids. High Kwik boit ii 4 3/4", 1 dia Hijti Kwik boit ii 6". Addition for 8" joints					ş	2,91
500-009							
	Addition Factory-welded miters: Including time and material (pounds of materials, pounds of tube/pipe, pounds of bent plate, Hardward, 3/4 dia. X 6* Headed Studs, pounds of hot dip galvanized finish, Standard Hop Primer, 3/4 dia. Hith Kwik bot II I 4 3/4*.1 dia. Kwik bot II 6* and factory mitered (pints.)					s	27
5500-010	Purchasing of the wait and floor fire barrier for the selsmic expansion joints. Supply F.O.B. fire proofing as described on sk-84-r Includes 160PF2018F/CF 12-6 joint 2hr pyroflex floor the barrier, 34tf PF2018					s	13,32
5500-011	CW 12-6 joint 2hr pyrollex wall fire barrier, 8 VF8/FB transitions  Modify structural steel beam (W27x114) per Sketch						
	79, to eliminate conflict between retunda cone and bridge.					\$	1,22
5500-012	Furnish and Install 2 ea. Structural tube steel (TS 3 x 5/16 x 5'-0") per RFI 534. This provides support for rolling grille soffit at plan counter.					\$	2,92
5500-013	Furnish and install Structural tube steel support for glass window walls behind plan counter on 1st floor, per RFI 611.					\$	6,51
5500-014 5500-015	Modify lavatory support brackets Credit for deleting elevator sill angle					\$	53 (3,06
5500-016	Addition of shims and modification of plan check					\$	69
5500-017	Work on Elevator screens					\$	70
5500-018	Field welds on rejected factory welds on rotunda skylight					\$	53
5500-019 5500-020	Provide a floor opening on 4th floor for utilities, Modify plancheck counter - concrete bushed at floor					\$	53 17
5500-021	conflict Add low wall supports in council chambers.					\$	1,37
5500-022	Modify decking for stair #7					š	20
5500-023	Addition of tube steel supports for glass window walls on 1st floor				. <u>-</u>	\$	6,51
5500-024	Structural steet shop drawings furnished for west entrance canopy					\$	1,24
5500-025 5500-026	Gredit for deleting door guards Modify structural steel W27x114 per sketch 79			l		\$	(1,09 1,22
6500-027	Add tube steel above plan check counter to support rolling grille					5	2,92
5500-028 5500-029	Furnish 4 fixed ballards for site improvements					3	1,35
5500-030	Modify tube steel in low wall at stair #7 Credit for changing stair #4 guard rail to a grab rail	(\$6,466)	Misc. Metal	ļ		\$	86
5500-031	Add deck supports above elevator #2. Design detail	\$1,014	holds Misc. Metal	<del> </del>			
5500-032	was not in original plans.  Additional labor to remove & relocate manifit gate and to install roof vent support frame at top of elev	\$2,316	holds Misc Metal holds			-	
5500-033	shaft Notch tread pan 1/4" for all posts on rading of stair #6	\$710	Misc. Metal				
5500-034	to resolve a field fitup problem.  Credit for revisions to projector screen seismic	(\$2,488)	holds Misc. Metal	·		┝─	
5500-035	supports per detail 6/A 10.20 Fabricate and install 3 metal stairs (3 steps each) in	\$12,495	holds Misc. Metal	<del> </del>			
5500-036	council chambers.  Fabricate and install galvanized guardrail for wall at	\$6,739	hoids Misc Metal	-			
5500-037	narane remp Fabricate and install elevator #2 platform	\$8,511	holds Misc, Metal	<del> </del>		<del> </del>	
5500-038	Fabricate and Install 66 linear feet of ramp hand	\$4,247	holds Misc. Metal	<del> </del>			
5500-039	railing above garage ramp @ sidewalk. Fabricate and install 41° guard rail above ramp		holds Misc. Metal		!		
			holds Misc Metal			-	
5500-040	Fabricate and install handicap ramp railing at library driveway sidewalk.	\$4,344	holds				
5500-041	Fabricate and install framework for trash enclosure	\$7,235	Misc. Metal	1		J	
			holds				
5500-042 5500-043	Raise counter support brackets @ public counter per field work order #258 penetration on bent plate @ stair #4.		holds Misc Metal holds Misc Metal			-	
5500-042	field work order #258 penetration on bent plate @ stair #4.	\$857 \$165	holds Misc Metal holds Misc Metal holds				
5500-042 5500-043	field work order #25B	\$857	holds Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal				
5500-042 6500-043 5500-044	field work order #258, penetration on bent plate @ stair #4.  Modify balcony rell for metal panel installation.  Furnish FOB plate for council chambers gallery.  Furnish FOB form lock 18GA, metal deck with radius	\$857 \$165 \$1,471 \$269	holds Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal				
5500-042 6500-043 5500-044 5500-045	field work order #256 penetration on bent plate @ stair #4.  Modify balcony rall for metal panel installation.  Furnish FOB plate for council chambers gallery.	\$857 \$165 \$1,471 \$289 \$1,570 \$4,328	noids Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal holds Misc, Metal holds Misc, Metal holds Misc, Metal holds Misc, Metal holds Misc Metal				
5500-042 5500-043 5500-044 5500-045 5500-046	field work order #258, penetration on bent plate @ stair #4.  Modify balcony rall for metal panel installation.  Furnish FOB plate for council chambers gallery.  Furnish FOB form lock 16GA, metal deck with radius cut for dals.  Furnish and install holst in pump room.  Remove scaffolding from stait #6  Credit for deduct for deletion of rail around brace.	\$857 \$165 \$1,471 \$289 \$1,570 \$4,328 1,026	noids Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal holds Misc. Metal holds Misc. Metal holds Misc Metal holds Misc Metal holds				
5500-042 5500-043 5500-044 5500-045 5500-046 5500-048 5500-049 5500-050	feld work order #258 penetration on bent plate @ stair #4.  Modify balcony rall for metal panel installation.  Furnish FOB plate for council chambers gallery.  Furnish FOB form lock 18GA, metal deck with radius tox for dals.  Furnish and install holst in pump room.  Remove scaffolding from stait #8.  Credit for deduct for deletion of rall around brace frame.  Re-install glass handrall angle brackets to clear reluring stud wall framina.	\$857 \$165 \$1,471 \$289 \$1,570 \$4,328	noids Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal holds Misc. Metal holds Misc. Metal holds Misc. Metal holds Misc Metal holds				
5500-042 5500-043 5500-044 5500-045 5500-046 5500-047 5500-048 5500-049	field work order #258, penetration on bent plate @ stair #4.  Modify balcony rall for metal panel installation.  Furnish FOB plate for council chambers gallery.  Furnish FOB form lock 160A, metal deck with radius out for dals.  Furnish and install hoist in pump room.  Remove scaffolding from stair #8.  Crede for deduct for deletion of rall around brace frame.  Re-install glass handrall angle brackets to clear	\$857 \$165 \$1,471 \$289 \$1,570 \$4,328 1,020 \$1,245	noids Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal holds Misc. Metal holds Misc. Metal holds Misc. Metal holds Misc. Metal holds Misc. Metal				
5500-042 5500-043 5500-044 5500-045 5500-047 5500-049 5500-050 5500-050 5500-051	feld work order #258 penetration on bent plate @ stair #4.  Modify balcony rall for metal panel installation.  Furnish FOB plate for council chambers gallery.  Furnish FOB form lock 18GA, metal deck with radius tox for data.  Furnish and install holst in pump room.  Remove scaffolding from stait #8.  Credit for deduct for deletion of rall around brace frame.  Re-install glass handrail angle brackets to clear rolunds stud wall framina.  Additional stainless steel.	\$857 \$165 \$1,471 \$289 \$1,570 \$4,328 1,025 (1 275 \$ 1,245 \$3,48	holds Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal				
5500-042 6500-043 5500-044 5500-045 5500-046 5500-047 5500-049 5500-050	feld work order #258 penetration on bent plate @ stair #4.  Modify balcony rall for metal panel installation.  Furnish FOB plate for council chambers gallery.  Furnish FOB form lock 18GA, metal deck with radius to the for data.  Furnish and install holst in pump room.  Remove scaffolding from stait #8.  Credit for deduct for deletion of rall around brace frame.  Re-install glass handrail angle brackets to clear rolunds stud wall framma.  Additional stainless steel	\$857 \$165 \$1,471 \$289 \$1,570 \$4,328 1,025 (1 275 \$ 1,245 \$3,48	holds Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal holds Misc Metal				

	l l	HOLDS OR UNI	BOUGHTS	OTHER C	CIP PROJ	ECTS		DJECT NGENCY
Change Order	•		ł	ŀ	l			
500-057	Description 8 Each, Stainless Steel plates for the South Plaza	amount	Description	amount		CIP project description	£IT	iount
	Fountain lets	49	5					
500-05B	Furnish and install guide rail per SK-2528 under Stair #4 for Title-24 regulæments,	\$ 977		1				
500-059	Stainless Steel Angle for Stair #1.	\$ 4,272						
500-060 500-061	Close gap at bottom of Stair #5. Relocate guardrail to provide clearance between		ļ	- <b> </b>		·- <u></u>	\$	84
350-001	stone and rait at Garage Ramp.			1			\$	708
	ONE WORK PLACE							
1	File/File pedestal unit for private office returns (19	\$7,838	FF&E holds					
	total)	\$4,006	FF&E holds	-				
	File cabinets (10), cashier stoole (2), change in work tables (2) in word processing	\$4,000						
3	Furniture (freestanding) storage from April 2002 to	\$12,567	FF&E holds					
	July 2002 @ \$3,147 per month due to extended project schedule				[			
	Private office keyboard trays	\$4,68	6 FF&E holds C FF&E holds			·		
<u>5</u>	Council Office Credenza Cost for storage of chairs August 26 through	\$1,01	U PPAG HOUS					
	September 17, 2002 Fourteen (14) additional 4-drawer lateral files for	2,518						
,	Planoing File Area, 2nd Floor.	4,182						
В	Modfication to desk returns at Offices 373, 372, 370,							
a	Additional furniture items for Offices 353, 354, and	\$1,280						
	355, including associated labor.	\$ 11,828						6.40
<u>10</u>	Provide (1) Mail Credenza for Council 3 additional chairs for executive session room		<del> </del>	-		· · · · · · · · · · · · · · · · · · ·	\$	2,18
	a positional strains of decounty goods from						J	
	OFFICE PRODUCTS PLUS INTERIORS		1				1	
1	Furniture storage due to extended project schedule	\$1,353	FF&E holds				1	
2	(from 3/1/02 to 7/31/02)		<del> </del>	-}		<del></del>	<del> </del>	
	September 2002	541		_	,			
				1				
	Pacific Water Art			1				
	Fountain Mechanical Pacific Water Art reduced their bid price by \$35,000. In addition, a credit of			1			<u> </u>	
	their bid price by \$35,000. In addition, a credit of \$1,600 was provided for using fibergrate grating	1		\$ (	38,800)	Pond Renovation (# 8141)		
	Instead of stainless steel KD grating.	l		1			<u> </u>	
2	Add hydrostatic relief system below pond liner to			s	7,000		ĺ	
<u>_</u>	eliminate uplift due to groundwater.  Add pond liner & gravel (deleted from Shooter &		·	5	55,500	D 1 D (C)D #9444)		
	Butts contract) net savings of \$1000		ļ			Pond Project (CIP #8141)		
4	Epoxy concrete sump wall located in the garage fountain room for the fountain pumps	\$5,000	Fountain hok	ds				
5	Granite for front and back wall of waterfall wall. This						ļ	
	work will be deleted from previously approved change order from Carrara (\$46,248)	1		\$	35,500	Pond Renovation (#8141)	ļ	
6	Grout and level outside deck	\$ 8,000		Į.	42094			
	Delete Pond Liner and Gravet Replace pond liner & gravet w/40 mll PVC and 3*	(\$55,500	D)				<del> </del> -	
	color concrete	\$ 68,500						
- 9	Furnish & install fountain well cap. Final cost for stone cap at Fountain well requires	\$ 20,000	)	-			-	
10	additional appropriation of \$1,635 00, previously	1	1	1		Pond Renovation (#8141)		
	appropriated \$20,000.00. Granite Tile Cladding @ Light Wall.			_  <u>\$</u>	1,635		5	24,00
12	Credit for usage of City provided debris box	·					\$	(66
	PARTITION SPECIALTIES		1	1			f	
	Furnish and install carpet tiles at access flooring only							
	Rooms 167 & 168.	\$ 5,567	<u> </u>	_			├	
2	Repair and patch dip on concrete floor in Committee Room, to provide smooth transition with raised floor	<b>'</b>					s	1,60
	Tabling to provide a state of the state of t	.		_			Ľ.	
	Preston Pipeline							
1	Delete storm drainage pipe and mannoles from							
	contract. Contractor has demobilized and work could not proceed because of ramp delays. The		1			İ	1	
	ramp issues have been resolved and a remobilizatio	\$ (29,000	,,	1				
	cost would be incurred if Preston comes back. This	(20,000	"	1				
	work has been negotiated with Division Two who is on site and can actually do this for much less	1	1	1				
<del></del>	ļ	I					├	
	ROLLIE FRENCH	<u> </u>		_		<u> </u>	<u> </u>	
9200-001	Bulletin #7 Orywall revisions - added drywall						s	70,51
9200-002	installation to fourth floor Plastering and Installation of Aluminum Reveals at		<del> </del>	_			1	
	Rotunda Wood in this area was removed as part of	s 200,00	3				\$	18,50
	a value engineering effort at which time \$200,000 was set aside for this work.							
9200-004	Furnish and install the additional edge of slab fire-	\$ 52,00	0	1				
9200-005	stopolog. Bulletin #3 revisions						\$	3,6
9200-006						[	\$	20,4
9200-007	Time & Materials structural steel freproof patching Added plaster at roof screen (sketch 1678)	-					15-	61,0
9200-008	Added fireproofing to accentric braces throughout	1		_			s	23,2
9200-009	building based on RFI #426. Furnish labor and materials for support walls at			- <del> </del>		<del></del>	·	13,4
	council chambers	<b> </b>	<b></b>				\$	
9200-010	Additional fireproof patching at various locations throughout building	1	1	-		L	\$	29,2
9200-011	Furnish labor and materials for additional revisions to	p	J				1.	
	the council chambers, reframing of the rotunda, counter support brackets.	1		1			<b>\$</b>	33,2
9200-012				$\neg$			15	22,0
9200-013	Remove water damaged sheetrock and insulation Shaft wall repair at elevator 1 based on time and		<del> </del>	<u> </u>				
	materials						\$	6
9200-014	Installation of shaft wall at elevator vent room 531						5	1,4
9200-015 9200-016	Fire tape shaft wall at 4th floor installation of metal stud framing SKS 76 at 1st floo	,	- <del> </del> -				\$	8,8
	fow wall fit. Glass wall	<b> </b>				-	1-	2,6
9200-017	Wall furring per Sketch 71-18 Increase exterior wall installation to R19 value	<del> </del>				L	\$	2,2
9200-01B							1 .	7,1
9200-018 9200-019 9200-020	Remove water damaged material Framing for linear diffuser per RFI # 635	_	_				1.	

	ļ	HOLDS OR UNB	OUGHTS	OTHER CIP PRO	DJECTS	PROJECT		
Change Order	Description	amount	Description	amount	CLP project description		smount	
	Extended scaffold rental at rotunda (12/9 to 1/17)	ATBOSEK	Discription			\$	3,07	
200-023	Metal stud framing, added furring, patching					5	3,30	
200-024	Removal of material due to water damage (Hellwig)					\$	53	
200-025	Parapet wall framing above the council chambers					\$	2,08	
200-026	Premium time for Fireproofing (8/8/01)					\$	3,66	
200-027	Reinstallation of fiberrock (2) handrall 314 Reframe for display case in room 149					15	87 56	
200-029	Add framing around column J3 @ 3rd floor					\$	24	
200-030	Walt changes at electrical panels per RFI #500 Modify framing at chase wall per RFI #410			ļ	-	\$	5,63 5,11	
200-032	Revise framing to create offset @ 2nd floor east wall					s	4,00	
200-033	per RFI #658 Removal and replacement of water-damaged	\$44,412	Interior wall		ļ			
200.000	wallboard in elevator shaft. Work performed over a weekend, because elevator was shut down	<b>V</b>	holds	1				
200-034	Reframing of tellet accessory dispensers at 1st, 2nd & 3rd floors	\$3,541	Restroom access Holds					
200-035	Scaffolding rental at rotunda (2/20 thru 3/28), City with be backcharging other trades for 75% of this cost.	\$5,872	drywall holds					
9200-036	Scaffolding rental at council chambers (2/29 thru 3/28) City will be backcharging other trades for 76%	\$3,525	drywall holds					
200-037	of this cost Added framing at Rotunda per Sketch #72.	\$407	drywali hokis		<u> </u>			
200-036	Construct wall and soffit per Sketch 207a,b,c	\$1,130	drywall holds	<b> </b>	<b> </b>			
200-039	replacement of gypsum board for inspection at several locations	\$577	drywall holds	ļ				
200-040	Layout of floor supporting walls	\$461	drywall holds					
0200-041 0200-042	increased R-11 Insulation to R-19 insulation Complete firerating of shaft @ room 215 - plans	\$12,829 \$1,137	drywall holds drywall holds	1	<del>                                     </del>	-		
	were incomplete				1			
9200-043	Fireproof sealing of exterior gypsum board under council chambers	\$1,801	drywali holds	L				
200-044	Removal of sheetrock & framing to adjust public	\$758	drywall holds			_		
200-045	counter & removal of door frame 110 Add wall penetrations for rotunda lighting per Sketch	\$3,633	Drywall Holds	<b>—</b> —				
	145 for MEP equipment	i	·	.		_		
9200-046	Revise 2 1/2" metal studs to 3 5/8" metal studs at South West corner of council chambers due to wall height	\$5,889	Drywall Holds					
9200-047	Extended scaffold rent at rotunda due to extended project schedule (from 12/9 to Feb 28)	\$15,343	Orywali Holds					
200-048	I project schedule (from 12/9 to Feb 20) Interior wall framing revisions and added drywall at	\$3,620	Orywall Holds	İ				
	mechanical and plumbing rooms 406 & 409	ŀ	1					
9200-049	Low wall revisions at first floor offices (room 155) behind plan counter per RFI #765	\$5,054	Drywali Holds	1		1		
9200-050	Added shaft enclosure with 1 hour fire rated wall per RFI 488. Wall was not included in original plans	\$6,566	Drywall Holds					
9200-051	Added framing to encapsulate seismic bracing per	\$2,093	Orywall Holds	i		~		
0000 050	sketch 143 and RFI 532	\$3,736	Council	ļ	<del></del>			
9200-052	Additional radius framing at platform for council chambers dias per sketch 183 & SKS 78 This was	\$3,730	chambers	1		1		
	an omission on the original plans		holds		<del></del>	-		
9200-053	Added soffit at fourth floor per sketch 207C	\$3,071	Drywall Holds	'l <u>.</u>		_ I.		
9200-054	Replace waterdamaged drywall that had been	\$24,433	Drywall Holds					
	previously removed. Replacement was held up until building was wateriki]it							
9200-055	Furnish and install radiused closure at glass rails per sketch 153. Details not included in original plans.	\$8,060	Drywaii Holds					
9200-056	Add low height wall with horizontal return per sketch	\$8,396	Drywall Holds			1		
9200-057	154 Details not included in original plans.  Added a two hour partition wall between elevator #1	\$5,041	Drywall Holds		<del> </del>			
	and stair # 2							
9200-058	Revise framing in offices 152 and 155 due to various conflicts corrected with sketches - Ti Sa & b	\$3,207	Drywall Holds	•	]	-		
9200-059	RFI 708 added shaft enclosure 2 hr rated @ iocations where electrical pipe racks penetrate 2 hr	\$8,330	Drywall Holds					
9200-060	walls. Wall was not included in original plans. Reframe door opening at rooms 353 and 354 per	\$615	Drywaii Holds		<del> </del>	-		
	sketch SK-TI 25, due to fit up problem.		1					
9200-081	Drywall and framing changes due to new celling partition @ cierks file area per sketch - TI 43.	\$8,798	Drywall Holds	<u>'</u>				
9200-062	Revise framing and wall at 3rd floor elevator hold open smoke doors, due to conflicts with the elevator control panels, per sketch 216A-R1	\$8,429	Drywall Holds	9				
9200-083	Drywall and framing at 4th floor for deletiong of temporary wall, reframe K-brace, add Drywall to	\$21,150	Drywall Holds			_		
9200-084	exterfor walls, and framing of column Plaster work remaining to complete changes made by RFi 571 to mechanical room on 4th floor	\$4,015	Drywall Holds	3				
9200-065	Removal and replacement of water damaged	\$2,778	Drywall Hold:	s		_		
9200-066	gyosum board on 1st and 2nd floors  Fireproofing patching (Trade damage at clearstory, elev # 2 vent, under chambers, and 3rd floor)	\$14,153	Drywall Hold	s	-			
9200-067	Credit to delete lath and plaster at garage and 1st	(\$6,820	Drywali Hold	,				
	floor level	· · · · · · · · · · · · · · · · · · ·	. L					
9200-068	Removal of wall between rooms 167 and 168	\$984	Drywall Hold	S		_		
9200-069	Added framing, extend 1 hr fire rating to exterior wal	\$942	Drywall Hold	3		_ _		
9200-070	and 2nd floor  Extended scalloid rent at rolunda due to extended project schedule (from 4/1/02 to 4/30/02)	\$5,683	Drywall Hold	6		$\top$		
0000 674	I '		Down No.					
9200-071	Extended scaffold rend at council chambers 4/1/02 to 4/30/02)		Drywall Hold		1	- 1		
9200-072	Change order savings on PCCO's #9200-007, 9200-	(\$107,791	) Drywall Hold	s				
9200-073	010, and CCO's # 9,10 17,19,21,24 Credit to delete lath & plaster between 6 and 4 lines	(7,236	·					
	@ garage & 1st floor levels							
9200-074	Replace edge of slab firestop assembly that was	12,794	·	_		1		
9200-075	removed on T&M due to water damage Furnish & install R-19 insulation pinned to underside	9,957	<del> </del>	<del> </del>	<u> </u>	- -		
	of decks at rooms 233, 234, 314			-				
9200-076	Install light pocket soffit framing and drywall per 10/A10 20	16,249	'					
9200-077	Demo existing 2 hr column and reframe per SK-	3,417	,		1	-1-		

		HOLDS OR UNE	OUGHTS	OTHER CIP PR	DJECT8	PROJECT CONTINGENCY
Change Order			i .		1	
#	Description	amount	Description	amount	CIP project description	amount
200-079	Frame wall per SK-185B at mop sink in 103B Frame new wall for door 248A	1,968 1,571				<u> </u>
200-080	Rework framing at column at south end of public	5,310				
200-081	counter for new door added by City Staff Replace water damaged insulation @ council	2,190				
	chambers Production loss to insulate exterior walls	0.000				ļ
9200-082 9200-083	Ramova vapor barner @ 2nd floor to install re-	3,996 316		<del> </del>		1
	firestopping (due to waterdamage)					
9200-084	Removal of gypsum board, reframe door openings  @ councilmember offices for new sidelight doors	3,435				
					. <u> </u>	
9200-085	Accoustical Sealing Ext wall @ council chambers	3,528		1		
200-086	Install stick-pin insulation under roof (Back charge to	7,760				
200-087	Insul-crete) Upgrade R-11 to R-19 insulation under deck	848				· · · · · · · · · · · · · · · · · · ·
200-088	(hackcharge Insul-crete) Upgrade level 2 firish to level 4 in 4th floor original			ļ		
9200-088	contract area as directed by City	11,020				
9200-089	Caulking interior & exterior @ plaster & windows	15,250				
9200-090	(partial backcharge to Painting Contractor) Scalfold rent@ rotunda 5/1 to 7/1(partial backcharge	11,744				
9200-091	to Sasco, Fetzer, ACCO) Council chambers scaffold rental from 5/1/02 to	2,274		·		
9200-091	5/20/02	2,214				
9200-092	Frame new wall per RFI 839 and Sketch 238 added	6,811				
9200-093	(wall Construct curb per Sketch 139 @ guard rail section	2,321	·	·	1	1
	Ø stairs			<u></u>	<b></b>	
9200-094 9200-095	Frame new horzontal shaft wall at parage Frame new soffit drop at stair No 1 and No 2 and	6,981	<del></del>		-	
	bulkhead @ 2nd flior walkway					
9200-096 9200-097	Reframe Public Counter Fireproof patching of Irade damage	361 8,173		<del> </del>		
9200-098	Union labor hourly rate increase, additional foreman	000,00		` <u> </u>	-	
	for extended schedule and additional scope increases	1			1	
9200-099	Framing and drywall revisions at Room 109, due	\$ 23,528	Drywall Holds			
	eliminate acoustical problems into the council chambers					
9200-100	Reframe public counter due to minor conflicts	\$ 361	Drywall Holds			
9200-101	Fireproof patching due to trade damage (costs will	\$ 8,173	Trade	<del> </del>	-	-
0200-101	be distributed to contractors working in building). This		damage holds			1
9200-102	Item is repeated see 9200-097 Install 2 hour rated soffit at stair #2 (4th to 5th floor).	\$ 625	Drywall Holds	ļ		
	Soffit was not shown on plans	L				-L
9200-103	Install drywall and taping in lieu of railing at k-brace in council chambers (\$5,000 cost savings)	\$ 978	Drywall Holds	·		İ
9200-104	Framing and drywall revisions at 2nd floor drinking	\$ 1,562	Drywali Holds	-		1
9200-105	fountain, for code compliance. Framing and drywall to provide additional soffits on	\$ 9,678	Drywall Holds	ļ	·	- <del></del>
	3rd and 4th floors not shown on plans.	.				-
9200-106	Framing and drywall to provide light soffits to rooms 111 & 112 Work not shown on plans.	\$ 1,684	Orywall Holds	i		i
9200-107	Revise framing at room 165 to address an 8" offset	\$ 690	Drywali Holds		1	
9200-108	at wall Provide drywall closure at wall per sketch #231, due	\$ 2,540	Drywall Holds			
	to design error/ommission.			_L		
9200-109	Provide drywall inside rotunda @ 2nd floor per sketch 232H.	\$ 7,544	Drywall Holds	i		İ
9200-110	Additional framing & drywall @ sunscreen per sketch	\$ 5,174	Drywall Holds		<del></del>	
9200-111	233B. Work not shown on plans Additional framing & drywall per sketch 224A-C &	\$ 4,751	Drywall Holds			
	RFI 684 Work not shown on plans.					
9200-112	Provide framing & drywali for shaftwall & FSD penetration. Work not shown on plans.	\$ 4,499	Drywall Holds	·		]
9200-113	Trade damage fireproofing patching on Council	\$ 11,025	T	<del>                                     </del>		1
	chambers, 4th floor, 2nd, and 3rd floor. (to be backcharged to other trades)		1			
9200-114	Removal of water-damaged sheatrock on 1st and	\$ 1,267	·			
9200-115	second floor, (50% back charge to Hellwig) Fireproof patching (trade damage) at clearstory, at	\$ 3,128				
9200-115	elev #2 vent, ext wall under chambers. To be	3,120	'	1		1
0000 440	backcharged to other trades	\$ 1,491	<del>-</del>	-		
9200-116	Replacement of water damaged gyp Board on 3rd floor at oir shaft					
9200-117	Upgrade R-11 Insulation to R-19 insulation under	\$ 800	]			
9200-118	deck Misc re-framing and caulking	\$ 4,544				
9200-119	Horizontal Shaft wall enclosure @ room 166. Work			1.		
9200-120	not shown on plans Completion of 4th floor columns sheet rock and	\$ 4,848	<u> </u>	-		
	finishing at City request		6 Drywall holds	<del> </del>		-
9200-121 9200-122	Extended scaffold rent at rotunda (1/18 thru 2/28) Gredit for deletion of Wing Walls @ lobby	(\$1,29)	31			
9200-123	Credit for deletion of decorative finish @ roll up	(\$3,34)				
9200-124	Frame, rock and tape drinking fountain wing walls @	\$ 528	3	- <del> </del>	-	
9200-125	room 407 Credit for deletion of framing and sheetrocking the	(\$39,63	<u> </u>			
	hard ceiling throughout the building		1	_	<u> </u>	
9200-126	Plaster CMU walls at elevator lobby	\$3,14 \$6,18				<del></del>
9200-127 9200-128	Additional framing and taping at Stair #1 Repair Shaft wall @ room 109	\$2,52	7			
9200-129 9200-130	Fire Rating ext wall @ rooms 167, 168  Miscellaneous drywall patching to fix walls where	\$3,77 \$1,16		<del>-</del>		
<b>9</b> ∠UU-13U	cable outlets were relocated, and air return	\$1,10	<u>"</u>	ĺ		1
	relocations were made in rooms 342, 350 and 363		1			
9200-131	Duct wrap for sound control room 109	\$1,29	06			
9200-132	Frame opening for Fire Extinguisher opening @ 4th	\$ 20				
9200-133	floor, not included in contract scope  Miscellaneous framing to patch holes on rooms 149	\$3,10	32	-	- <del></del>	-
	150. These holes were cut for utility penetrations by				!	
9200-134	other contractors Miso patching, framing insulation above cast glass	\$ 3,54	9		+	+
Ĺ	window					<del> </del>
9200-135	Enclosure of electrical conduits @ elevator machine room 04	\$ 1,452	<sup>2</sup>			
		4				
9200-136	Framing under floor opening @ chambers required for closure of	\$18	28		1	

	l	HOLDS OR UNB	OUGHTS	OTHER CIP PRO	JECTS	CONTINGE	T NCY
Change Order			D	i	Cta (a-t desemble)	amoun	
# ************************************	Description	amount \$ (4,354)	Description	amount	CIP project description	moun	_
200-138	Credit for prime & repaint patched areas at 3rd floor due to Sheet rock repairs	\$ (4,354)					
200-139	Credit for paint patches @ 2nd floor south side do to	\$ (3,761)					
200-140	tager patchwell Paint wall end to end Credit for repainting the rotunda due to repatching	\$ (3,118)				<del>- </del>	
9200-141 9200-142	Credit for repriming retunds ceiling Additional drywall work at 2nd Floor: Extra layer at	\$ (1,037)					
9200-142	Rotunda and cutout/frame opening at east telecom			1			
200 4/2	room.	\$ 513 1,398	<del> </del>				_
9200-143 9200-144	Additional taping due to alteration to Room 219.  Additional drywall work at 1st Floor: Electrical	2,522			i		
	patches and patching at roll-up door.	2,522			<del></del>		
200-145	Added drywall and taping for top of handrail wall on 4th Ficor.	\$ 3,083					
200-146	Metal stud framing for slab replacement per SKS-88						
200-147	Trade damage throughout hulden	\$ 2,294 \$ 20,000				+	
9200-148	Trade damage throughout building.  Drywalt repair at roll up door @ public counter	3 20,000				\$	59
200-149	Drywal patching around elevator call light					\$ 4	62
9200-150 9200-151	Repair trade damage @ Rotunda Plaster Repath retunda plaster 1st & 2nd floors					\$ 1	1,08
9200-152	Backcharge for use of debris boxes					\$ (16 S	6,59 6,00
9200-153 9200-154	Caulking Glass Rails Credit for interior caulking					" (\$ (7	7,36
9200-155	Credit for wall framing and drywall on 3rd floor.						0,00
	ROYAL GLASS						•
8900-001	Furnish & Install Glass Door Hardware - exterior	\$ 126,328	Glazing				
8900-002	doors and Brite-vue door hardware Furnish and install aluminum perforated ceiling in						
0000-004	Council chambers for \$64,239 and and furnish and	\$ 136,639	Misc. Melai		ļ		
	install entry canopy at west building entrance for	* (20,008	miso Mela!	!			
8900-003	\$72,400, Total change order is \$136,639. This work includes labor and materials to install	<del>                                     </del>		<del> </del>	<del> </del>	-1	-
	Interior glass, clerestory glazing, interior aluminum	\$ 38,500					
	framed doors, fire rated frame and glazing at the retunda cone			l			
8900-004	Furnish Material - Doors, Frames, Hardware	\$ 155,688	Doors /				
8900-005	(126.328 + 155.686 = \$282.016)  Door and Hardware Modifications (Due to redesign,	, ,,,,,,,,	Frames			_	
0900-000	damaged, revise size, modify door frames and		]			\$ :	2,69
	deletion of existion dogs)			1			_
8900-006	Upgrade standard hollow metal doors to Rite doors on third floor labby areas	İ				\$ 10	0,76
8900-007	Add 1200 sq. ft of light bronze panels on the east	\$20,787	Exterior wall				
	elevation, including mise clips, vapor barrier and caulking		holds			1	
8900-008	Temporary doors for construction storage use at	\$498	Door holds				
8900-009	rooms 404, 216 & 115 Furnish galvanized metal frames for the trash	\$3,424	Door holds		<del> </del>		
0900+008	enclosure,						
8900-010	Furnish four doors with sidelights @ councilmember offices	\$2,444	Door holds	ľ			
8900-011	Furnish push buttoms for (3) inside handicap doors	\$3,650	Door holds		-		
		200 101	B				
8900-012	Furnish and install motor louvers covers and blind pockets	\$29,424	Door holds	1		1	
0900-013	Fabricate & install sidelights @ councilmembers			ſ		ĺ	
8900-014	offices Fabricate & install aluminum louvers @ generator	9,156					
	Mail Annicate & itizian similindin indivers & Benerator	5,255					
8900-015	Provide labor to fabricate louver covers and install	\$ 8,958	Mechanical Holds				
8900-016	motor operators See CCO 8900-012 Changes for interior doors 100A and 229	\$ 11,670	HOUS				_
8900-017	Furnish & Install motor operators for louvers on 4th	\$ 38,382					
8900-018	Akunimum Break Shape for Cast Glass @ North	\$ 3,358		·			
	entry FWO 50 to fix design problem between ceiling						
8900-019	Replacement damaged sidelight glass @ south	\$ 13,051	<del>                                     </del>	İ		-	
0000	entry. City was not able to establish trade who	13,007					
8900-020	damaged glass	(\$72,400	J		<del></del>		
8900-020	Deletion of West entry canopy Furnish & install flat aluminum strap at Rotunda on	\$ 1,943		···	<u> </u>		
8900-022	2nd floor curtain wall area.	\$ 1,287		<del> </del>	<b>-</b>		
08004022	Remove and reinstall windows for holsting & stocking carpet into 2nd and 3rd floor	1,287		1			
8900-023	Hardware changes at Doors 006, 102X, 107, 108,	40.000	1			1	_
8900-024	208A/208B, 210, 357, 367A/367B Changes to hardware at Doors 208A/208B & 210	12,982		<del> </del>	<del></del>		
	1	110	ļ	<b>.</b>	<b> </b>		
8900-025	Change to hardware at Doors 153, 147, 248A, 356, 360, 214, 363, 364, 365, 366, 202, and 244A.	1		1	1		
L		5,916	ļ				
8900-026	Furnish and install clear anodized aluminum pipe	4,282					
8900-027	wraps at 2nd Floor handrail Change swing on (2) doors at 4th Floor	\$ 2,500					
8900-028	Miscellaneous backcharges for use of City rented						
8900-029	Additional changes to Raise curb to 1'-8", Raise	{20,650		1	<del> </del>		_
	windows at 4th Floor, Demol and re-frame windows	1		1		<b>  1</b>	17,6
	37 & 38 (4th Floor North), and Add backing at paraget for handrail.	1					
8900-030	Correction to door hardware changes cost from 09-	1				5	6
8900-031	17-02	ļ	<del></del>		+	<u> </u>	1.7
8900-032	Install floor mounted door stops Install end caps on room 208			1		_  š	4
8900-033	Clean & reinstall window glass on 3rd floor window			1	1	\$	1
8900-034	Install breakmetal cover exposed framing at council	-			<del> </del>	5	9
	gallery	ļ		-	ļ. <u>.</u>	- s	
8900-035 8900-036	Change two doors glass @ lire administration Install multion on glass @ stair #4 Engineering	·	<del> </del>	<del>                                     </del>			- 6
8900-037	Install tempered glass in door @ public counter					3	Ì
8900-038	Furnish & install pipe wrap/rods covers on second	1		1		s	4,1
8900-039	Credit to accept panels as installed on the exterior of	,	1			S (1	12,7
	the council chambers	ļ	<del> </del>		<del></del>	_	
8900-040	Credit for overcharges on previously approved change orders		-		1	\$ (1	13,6
<del></del>				1	1		_
	SASCO	1	1		1	1	

	<u> </u>	HOLDS OR UNB	DUGHTS	отн	ER CIP PRO	JECTS		ROJECT TINGENCY
Change Order			December 1	l		CEP project description	_	mount
#	Description Security System - including cameras, software,	emount	Description	ame				mount
6000-002	switchboxes, and hardware			\$	251,729	City Hall Technology (#8142)		
8000-003	Emergency Generator - 300Kw with 380amp at 480 Volt. Will provide power for elevators, computer						1	
	system, electronic key bidg access, fire/security			\$	124,661	Tele-communications (#8093)	ĺ	
	alarms and safe evacuation- Concrete pad to be installed by others					(,	l	
6000-004	Additional Patio Receptacies - wiring, conduits and			\$	4,674	Pond Renovation (#8141)		
6000-005	receptacles added in patio Dimming System - added light dimming system at			╢				
0000-000	conference rooms with Audio/Visual technology.			\$	16,443	City Hall Technology (#6142)	ĺ	
8000-006	Distribution Systems revisions - furnish and install			-			i	
	electrical switchgear & feeders. Price includes credit			1			\$	22,728
6000-007	for original workscope in contract.  Furnish & Install Tele/Data Infrastructure (building			5	89,852	Tele-communications		
6000-007	conduits, junction boxes) Furnish & Install Tele/Data Service Entrances					(#8093) Tele-communications		
	(exterior pullboxes & conduits)			\$	21,330	{#8093}		
6000-008	Provide credit of \$43,807 for lower actual cost of furnishing light fixtures Bid allowance was \$450,000	\$ (43,807)				İ	ĺ	
	and actual cost is \$406,193			╄.		Tele-communications	-	
6000-009	Furnish and Install Telecommunications Wiring			5	245,157	(#8093)		
6000-010	Work to furnish and install the A/V infrastructure per			\$	175,000	CIP #8142 City Hall		
	Sasco Electric's and Ove Arup's drawings. Total \$175,000 + \$46.099 = \$223,099			1		Technology	Ĺ	
6000-010				\$	48,099	CIP #8093 Telecomm.		
18000-011	Furnish and install the PacBell box and cover at new grade.			\$	1,657	CIP #8143 - Parking & Circulation Project		
6000-012	Furnish and install a complete fire alarm system.			1			s	17,675
	(Installed and wired all fire atarm control panels and fire atarm geopheral devices)			L		<u> </u>	<u>                                     </u>	11,07
16000-012	Update fire alarm drawings to match current			1			\$	3,58
6000-013	backgrounds Furnish and Install branch power & devices per	<u> </u>		+		†	<b> </b>	
	Sasco electrical drawings dated 8/15/01. (This quote	\$ 71,320	Electrical Holds	ŀ			1	
	includes a deduct for the scope of work that was included in the original bid)		nuids	L				
16000-013	Install light fixtures per electrical drawings E2.0 -			l			\$	215,04
16000-014	E2 5 dated 6/15/01 Relocate Main power switchboard from building to	\$ 58,970	Electrical	╁			i	
16000-015	PG&E transformer area. Provide wiring, conduits and boxes for Site Event	4 40,070	holds	-		<u> </u>	-	
10000-010	power, data and switching controls. There are three	ļ		ł		1	}	
	outdoor locations for events: the plaza area and front			Ĺ		City Hall Technology Project (CiP #8142)		
	and back patios of the building. This also includes permanent power for holiday tree lighting.			1		1	ļ.	
10000 010	ceremonies.			\$	50,000		·	
16000-016	Provide wiring, conduits and boxes for Fountain lighting, power for pumps, controls and anomometer	i	Ì	ļ		Pond Project (CIP #8141)		
40000 047		ļ	ļ <u></u>	_  s	43,157	Parking Circulation (CIP		
16000-017	Install wire, conduits and parking lot light fixtures. Light futures to be provided by City.				17,145			
16000-018	Furnish and maintain generator for temporary		<u>-</u> -	Ţ-				-
	construction power Incl. Manlift and dewatering pumps. Fuel costs were \$42,176 and equipment			1			5	153,26
16000-019	rental and servicing was \$111.042 Audio/visual revisions included in Bulletin 27 which			╀		<b>ļ</b>		
16000-019	included two new floor boxes in council chambers		1	1			١.	
	and conduits between AV closet and council	1		1			\$	2,76
	chambers modifications per drawing AV6.01.		ļ	_ _			ļ	
16000-020	Furnish & Install additional fiber cables at various locations	[		ĺ		Ĺ	\$	12,89
16000-021	FWO #603 elevator temporary power & lighting			7			\$_	2,67 3,57
16000-022 16000-023	FWO #605 repair of street lighting Telecommunications Field work orders to add	<del></del>	ļ				<b> *-</b>	
	several data drops at lobby and other offices		ļ	Ş	4,225	i	-	
15000-024	Electrical revisions per Sketch 148 - first floor window revision			1			\$	30
18000-025	Revisions to Coffee room 215			_ _			3	2,98 5,17
16000-026 16000-027	Audio/Visual changes per RFI 767 Audio/Visual changes per RFI 731 & 732	<del> </del>	<del> </del>	-		<del></del>	5	30
16000-028	Add egress lighting at west entrance and north	\$23,175	Electrical	$\top$				
16000-029	entrance. Add F18A lighting at Video conf. Room.	<del> </del>	Holds	-			\$	1,24
16000-030	Added floor electrical outlet, wiring, conduits and	1	1	_			s	1,50
16000-031	switching at lobby, per sketch 50.  Additional conduit & wiring for front fountain (\$695)	<del> </del>		- -			1-	
	and replacement of electrical outlet/switch in elevato	ď		15	766	Pond Project (CIP #8141)		
16000-032	shaft (\$71), total = \$766 F14A additions of 6 lights per Sk-200 for lighting at		Electrical	- -		<del> </del>	1	
16000-033	West entry Respectfied F37 feature to replace F23 features 2	\$ 3,797.00	Holds Electrical	- -			+-	
	coucil chambers	\$ 2,385.00	Holds	_ _				
16000-034	Add F2-8 and relocate fixtures due to changes on room 354 per sketch T(5b	\$ 912.0	Electrical Holds	1			1	
16000-035		- U.L.V.	Electrical					
	Revision to F34 & F34A fixtures (additional F34A fixtures and two transformers @ council chambers)	s 7,576 0	Holds					
16000-036	Respecified F22 fixtures due to conflict with beam a	il	Electrical	-j-			1	
16000-037	Council Chambers  Respectied F30 fotures as per LSK-11 to change	\$ 1,748 0	Electrical	- -	·	+	-	
	fixtures w/out costume painting.	\$ (5,520 0	Hokis /	4		<u> </u>	-	
16000-038	EF4 flutures revisions(Delete 3-42 Watts and add 4- 70 Watts)	\$ 818.0	Electrical			1	_]	
16000-039	Fixture F36 revision and dimming as required per	\$ 4,416.0	) Electrical	- -				
	Graffik Eye submittal review Revisions to (2) south and (2) north futures	1	Holds	-  -		L	_l_	
16000-040	Repair/replace electrical outlets to allow access and			_ -			1	
ĺ	replacement of waterdamaged sheetrock in shafts &	77	d	1		ĺ	1	
16000-041	Power & Telco provisions @ 4th floor	2,91		_ -			1	
16000-042	Furnish & install additional bracketing and conduits,	,	-	- 1		1		
L	required due to detetton of ceilings in telecom rooms per City request )	4,52		_!_			_ _	
16000-043	Relocate I-boxes room 103	2,41	3	-			-	
16000-044 16000-045	Rework conduit in council chamber Rework tray in garage	2,10	5					
16000-046	Electrical rework on elevator	2.99						
16000-047 16000-048	Credit for respecified F20 fixtures  Fixture F36 revision and dimming as required per	1	-				$\top$	
ı	meeting with lighting architecht. Revisions to (2)	4,41	_ [	- 1			1	

	<b>j</b>	HOLDS OR UNE	OUGHTS	OTHER C	IP PROJ	ECTS	PROJECT CONTINGENC
Change Order			i		1	CIP project description	
6000-049	Description	amount	Description	amount		CIP project description	amount
0000-049	Furnish and Install new exit lights throughout building.		l		ļ		
6000-050	Original spec, did not provide backup batteries.  Grafik Eye revisions Dalmming system for council	3,148		ļ	-		
0000-030	chambers, council overflow and video conference		ļ	i	ı		
2000 OE4	room F14A additions of 6 lights per Sk-200 for lighting at	5,305		ļ <u>-</u>			
6000-051	West entry FWO 43	1,068		ļ			
6000-052	Switch F5 to F8 fixtures in Rooms 111 & 112						
	fixtures. Restocking was not possible. Charge due to design conflict	2,959		ł	1	ļ	
6000-053	Credit for deletion of FBA fixtures	(3,092)					
6000-054	Credit for respecified F30 fixtures as per LSK-11 to change fixtures w/out custom painting	(5,520)	<b>!</b>	1	J		
6000-055	Revision to F34 & F34A fixtures (additional F34A			<b>†</b>			
	fixtures and two transformers @ council chambers)	7,576		Į.	[		
6000-056	Respecified F37 fixture to replace F23 fixtures 2			·[			
6000-057	coucil chambers  Add F2-8 and relocate fixtures due to changes on	2,385	<b></b> -	·			
	room 354 per sketch TI5b	912	ļ				
6000-058	Respecified F22 flutures due to conflict with beam at Council Chambers	1,748	ĺ	ĺ	ĺ	İ	
6000-059	Change from F8 to F32 fecture due to error on	\$ 3,877	Electrical	l			
2000 000	specified fixture	\$ 4,396	Holds Electrical				<del></del>
6000-080	Add 5 E fixtures, conduits and wiring, for trash englosure and generator building.	\$ 4,390	Holds				
6000-061	Furnish & Install F-11 flutures (2) at rolunda, per	\$ 853	Electrical	1			
6000-062	sketch 182C. Respecified F18 fixture due to change to T-bar	\$ 2,320	Holds Electrical				
	celling.	l '	Holds	<u> </u>			
8000-083	Relocate 4 - 2" conduits at west entry due to elevation changes.	\$ 607	Ejectrical Holds	J		<u></u>	
6000-064	Provide temporary power for fountain mock up.	\$ 773	Electrical				
6000-065	Furnish, & install 2 additional conduits, including	\$ 1,308	Holds Electrical	<del> </del>			
	trenching & backfill, at the ramp for future use		Holds				
6000-066	Re-route conduit on room 219 to clear projector, due to design conflict	\$ 308					
6000-067	Add six power and telecom boxes in room 403.	\$ 2.226					
6000-068	Troubleshoot bad fiber strand in exist splice case	\$ 1,898					
	From strand from Public Works Bldg to City Hall. Request from City I S dept						
6000-069	Rework electrical outlets at rooms 357, 358	\$ 1,205 \$ 904		<u> </u>			
6000-070	Relocate chases & power for plasma screen in second floor lobby at City request	\$ 904	i				
6000-071	Lower strip fixtures on the 4th floor to accommodate	\$ 1,832					
	T-bar ceiling, due to design conflict.						
6000-072	Rework electrical installation in data rooms due to	\$ 1,272		<b>1</b>			
16000-073	removal of ceilings at City request. Premium time to install down lights in 3rd floor	\$ 436	ļ	-l			
	corridor, due to design conflict	l		<u> </u>			
16000-074	Rough Electrical wiring and conduit for site lighting.	\$ 50,000		ł			
	This will allow sidewalks and other work items to continue, until site lighting design is completed.	ļ	j	J			
	Another change order will follow, to provide fixtures.			1			
	and remaining electrical work for site lighting.			1			
16000-075	install 9 additional outlets on 6 circuits @ 4th floor for		Electrical hold	s			
16000-076	temporary offices Provide emergency power to Type EF4 fixtures @	\$1,000 \$2,71	u 4 Electrical hold	s			
	stairwell #6						
16000-077	Electrical changes due to ACCO's revisions to drawings	\$53,78	3 Electrical hold	s			
16000-076	Furnish & install electrical wiring, conduits and	\$ 1,001					
	magnetic locks for "smoke hold open" doors in rooms 363-366	]	1	}			
16000-079	Added data and receptacle at room 360	\$ 4B3					
16000-080	Relocate Switches in room 355	\$ 589 \$ 2,090					
16000-081	Furnish & install electrical conduits, wiring, and outlets for temporary City offices in 4th floor.	\$ 2,090	1				
16000-082	Furnish & install site lighting, including	\$ 325,000					
	engineering/design, trenching, cabinet panels, conduits/winng, and lighting fixtures	ł					
16000-083	Furnish & install Event power, including trenching,	\$ 75,000	-	\$ 2	5,000	CIP #8142 City Hall	
	outlets, pedestals, conduits/wiring, engineering/deskin, and panels			Į.		Technology	
16000-084	Furnish & install electrical associated with Pre-action	1	T	\$	12,229	Tele-communications	
	System, sensor ion smoke detectors, manual pull station, horr/strobe, bell, monitoring modules, and	Ī		1		(#8093)	
	monitor of waterflow, tamper switch, and scienoid	Į		1			
16000-085	yalve. Relocate electrical in Room 109 to accommodate	\$ 747	<del></del>	-			
,3000-003	shaft per details in field work order -123.	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		1			
16000-086	Additional partition furniture circuits per field work	\$ 1,395		-1			
	order -117.	1,080					
16000-087	Relocate under-counter refrigerator receptacles per field work order -125	\$ 834					
16000-088	Change electrical and data switch and outlet cover	\$ 653		-		1	
	plates to white color. Change partition furniture data	1					
16000-069	Add conduit for door hold opens at Rooms 353, 364	\$ 2,589					
	365, and 366.			-			ļ <u>.</u>
16000-090	Electrical associated with combining Rooms 167 and 168	\$ 5,638	']	1			
16000-091	Supply power to Louvers at Rotunda, FWO 46	15,71	5	1			
16000-092	Provide and install seismic racks at First Floor Telco Room	2,94	.4	1			l
16000-093	Provide and install (1) 4" underground conduit and		-	1			·
	pull string from Fountain Pump Room to Library	1	17.	1		1	ł
16000-094	Rework for HVAC Electrical	1,20		1			
16000-095	Furnish and install additional Library Parking Lot Ligh	\t		1			
16000-096	Upgrade Threshold Computer NT per IS request.	26,71	5		2.375	City Hall Technology (Project	
			<b> </b>			#8142)	ļ
16000-097	Furnish additional HID card readers at balconies per IS request.	1		\$	3,173	City Hall Technology (Project #8142)	1
16000-098	Provide/Install program for double-sided photo ID	·		\$	9,135	City Hall Technology (Project	· · · · · ·
16000-099	badging unit Design and installation of fire alarm dialer	\$ 2.216	<del>,  </del> -	+		#8142)	
	Provide security panel with transmitter for security	- 1-x x - x - x - 1°		5	4,397	City Half Technology (Project	1
16000-100	communication between City Hall and Police					#8142)	

		HOLDS OR UNG	8THDUO	OTHER	CIP PRO	JECT8	PROJECT
hange Order	Description	amount	Description	antovni		CIP project description	amenat
000-101	Credit for dejetion of CO #65 (Site Lighting Rough	\$ (50,000)		1			
	in). This work was included in another change order.	, ,		1			1
000-102	Add conduit and boxes for phone and data drop at Pump Room, Boiler Room, and Mechanical Room at	\$ 1,701	ļ	T			
3000-103	Roof Access Add Volce/Data inside Pump Room in Basement and Baller Room on 4th Floor. Add single volce line outside Mychanical Room for Roof Access.		,	\$	1,663	Tele-communications (#8093)	
000-104	Add (1) standard drop and (2) extra voice only at	\$ 1,122	<u> </u>	-		V:	-
000-105	Room 361.  Add Voice/Data drop to cube section on 3rd Floor for			- 3	836	Tele-communications (#8093)	-
000-106	fax and printer. Add chase for ACCO in Mechanical Room for Computer Feed to EMS Panel.	656	3				
000-107	Change out lamps for F-37 fixtures in Council	1,27					
000-108	Rework electrical and chases for data in Room 219.  Relocate (2) F3 to illuminate the "hand out" rack		ļ	\$	3,564	CIP #8142 City Haif Technology	<u> </u>
3000-110	area, in Room 219 and 113.  Repair conduit damaged by Installation of new driveway, Add 2° chanse and pull box at Sidewalk	49:		-			
5000-111	Relocate feeds to furniture for power. Data in Room 342 and add feed for power. Data in Room 160.	1,10	2	5	1,258	CIP #8142 City Hall Technology	
3000-112	Premium Time Only for work on August 30th & 31st.	\$ 8,838		<b>-</b>			
000-113 000-114	Premium Time Only for work on September 14th Additional Event Power.	1.87		5	8,000	CIP #8142 City Hall Technology	
3000-115 8000-118	Provide and Install (5) manual cull station covers  Additional Site Lighting, supply (1) Gardoo 20PT pole with (2) high-pressure sodium light fixture heads.	·					\$ 1,3 \$ 3,4
5000-117	Provide and Install (2) additional Type E5 uplights in			-			\$ 3,
8000-118	planter near upper pond Provide and install (1) exterior HID card reader on existing bollard at top of parking garage ramp.					· · · · · · · · · · · · · · · · · · ·	\$ 3,
6000-119 6000-120	Relocate telecom in Room 342 At Conference Room 168, Add (1) single data outlet						\$ <u>1,</u>
6000-121 6000-122	Add second wireless LAN drop at 3rd Floor.  Relocate conduit and wire in fountain pump room due to location of hoist		7	-			5
6000-123 6000-124	Add 120V to Air Handlers 1.8.2  Changes to card access system: additional motion detectors and door contacts.			-			\$ 8,
6000-125 6000-126	Relocate and add furniture feeds Rough kvinstall boxes and power for handicap doors						\$ 3, \$ 7,
6000-127 6000-128	Re-work electrical at Public Counter Relocate receptacles at Main Telcom Rooms						\$ 3, \$ 1,
6000-129 6000-130	Electrical changes in Elevator Pit #2 Electrical connection of Conference tables		-				\$
6000-131	Added plugmold in Room 249	- <del> </del>	<del></del>			ļ	\$
6000-132 6000-133 6000-134	Remove and reinstall light flutures in Council			-			\$ <u>7</u>
6000-135 6000-136	Chambers Replace (4) damaged Christy Boxes. Remove switches for installation of sound board.						\$ 8
6000-137	Add exit light at 1st Floor Stairway #2						\$
6000-138 6000-139	Chases for added gard readers. Electrician on-site for City Council Meeting.	-					5
6000-140	Electrical changes on City Council Chamber Seating  Backcharge for damage to roll-up door at Garage	j.					\$ 1
6000-141 6000-142	Entry Backcharge for use of debris boxes						\$ (2 \$ (13
6000-143	Backcharge for enclosure of conduits on elevator machine room	ļ	<u> </u>	_ _			\$ (1
16000-144	Additional temporary power costs to reflect actual costs for Generator Rental, Fuel, and Maintenance.						\$ 3
16000-145	Provide and install additional 100FT length of rope light at stage, including controller in weather proof box		-	_ _			S 1
16000-145	Test Fire Alarm System to Dispatch Center after hours.  Premium time only for work on Saturday, 09/14/02,		-	_			- s 1 s
16000-148 16000-149	to test fire alarm system.  Add pull station in Room 168  Remove and reinstall horms and strobes due to ner	- <del></del>		_			5
	soundboard			_ _		_	- s 1
16000-150 16000-151	Provide rough-in and wiring of Mechoshades Repair street lighting damaged by landscapers						\$
16000-152	Disconnect and remove panels in Library.						5
16000-153	Provide one (1) each Size 1, Size 2, and Size 3 Advantage contactor for future stock.						\$ 1
18000-154	Installation of capacitor for fountain backwash motor	or					\$
16000-155	Provide and install two (2) door contacts at double idoor to Community Room, includes cable required for additional contacts and programing system.						s
16000-156	Additional HID card reader at Starwell #2 (Door #122), includes terminal controller board, cable required, and programing for additional card reade	r.					\$
16000-157	Pull (2) voice lines for pay phones on Second Floor		-	_			- s
16000-158 16000-159	Pull (1) RG6 cable for rear AV room, Pull (8) CAT 5E "dala only" cables to fron and rear						\$
16000-160	AV Rooms Run (2) CAT 5E cables to Room 342 for	<del> </del> -				<del>                                     </del>	\$
16000-161 16000-162	Add cabling in Room 354 Pull (1) CAT 5E cable to locations on 1 East and 2						5 5
	Cast for a factors assess exclaim		1	- 1		1	1.5
16000-163	Relocate Data lack in Mayor's office						\$

ĺ	i	HOLDS OR UNB	OUGHT8	OTHER CIP PR	OJECTS	CONTI	INGENCY
hange Order	Description	amount	Description	gamount	CEP project description	ап	nount
	Religionate Highn Strobe in 1st floor					\$	. 849
1000-187 F	Relocate transformer from Room 213 to 214A.					\$	2,460 1,606
000-168 F	Furnish & Install sump alarms at elevators. Credit for Event Power rough-in (rough-in work was			1		\$	(48,913
	ncluded in change orders 66 & 132.) Relocate East Parking lot lighting		<del></del>	<b></b>	<del>- </del>	5	9,261
000-171 F	Provide 11 additional receptacles and data outlets at					\$	2,32
000-172 F	council dals Relocate roof conduits as directed by City.				<del> </del>	\$	1,200
1000-172	TODOSIO TODI GOTO DI GRADINO IL GALLI						
	SERVICE METAL PRODUCTS			<del> </del>			
	Furnish and install lockers for planning	\$ 2,860					
	commissioners. Provide FRP for Januar's Closets	4 040					
	Increase mirror height from 32" to 36" at all	1,940				T	
	restrooms	990 \$ 2,560	ļ		- <del></del>	<del> </del>	
	Add coat hooks at all restrooms  Net contract savings after completion of	\$ 2,560	ļ		·	s	(48
	miscellaneous change order work				·	Ľ	
ļ.	SERVICE PERFORMANCE			<del></del>		·	
	Final Construction Cleaning of building	\$ 24,044		<b></b>			
	Garage & Parking lot cleaning	\$ 3,630					
	SHEEDY HOIST	·			- <del> </del>	<del> </del>	
	Additional funds to pay for operator costs	\$ 3,034					
	SHOOTER & BUTTS			-  <del></del>		<del> </del>	
1	Credit to delete pond liner & gravel from contract			\$ (56,50	0) Pond Project (CIP #8141)		
2	Furnish and install miscellaneous improvements per Bulletin #35	\$ 19,000	<u> </u>				
3	Additional top soil and changes per Plan Revisions	01.00	J			1	
4	06/16/02, etc. Final landscape planting revisions and additional	24,000	<b>}</b> -	-		\$	10.00
	plants	ļ				<del>  `</del>	
	THYSSEN						
	Relocate conduits & rewire call box at third floor	\$ 2,724	Electrical Holds		1		
2	elevator #1, due to design error Maintenance of construction elevators (based on	\$ 5,000	rious	_ <del> </del>		<del> </del>	
	time & materials not to exceed)						
	WEIDNER SIGNAGE						
12	Workstation nameplates 4 Type N (clearance bars for garage) 6" dia. & 8	\$8,67	FF&E holds	-			
-	inches long & 2 Type "P" signs for Council Chambers		1,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	1			
3	Furnish & install "Milphas City Hall" Exterior	\$ 5,338	-				
	dimensional letters	i		_		-	
4	Additional signage for City Hall to meet code and functional needs.	\$ 8,832		1			
5	Credit for sign Types C.E.Q-2. Additional signs	\$ 465	]				
	needed: Type D, H, Q, R, Z-1, G-1b, B-2, S-3, R, Q U-2, and install Knox Box.	1	<u>.</u> L_			_[	
6	Fleid installation sign revisions and additional signs					\$	6
7	required for occupancy permit.  Core drill for installation of "Garage Hours" signage					s	4.
8	at top of ramp. Misc, revisions to signage, including additional	-				1	
	signage.					\$	4,0
	WW STEEL	-	<del> </del>				
	Furnish and install additional structural steel beams,					5	16,0
	to provide support for relocated HVAC system, on the Council Chambers roof.						10,0
100-002	Furnish and install additional miscellaneous structura	1				\$	50,0
	steel and metal decking required due to plan revisions	]				_	
100-003	Addition Fabrication Detailing required because the				1	\$	75,0
	structural steel plans were not final plans at time of awards.	_		_		<u> </u>	
	Steel Design changes due to bulletin 13 and other	1	(		1	5	41,2
greement	Architectural revisions	1				1	
kmendment#	"[						
	STUDIOS ARCHITECTURE						
	Provide additional design services for various elements of the building (\$126,205) and an		1		88 Parking Circulation (#8143	, .	126,2
	easement map preparation for Parking/Circulation	1		\$ 2,8	Parking Circulation (#814)	3) \$	140,2
	project (\$2,888) Amendment #6	<u> </u>					\$150,0
			+	_			
	TURNER CONSTRUCTION Provide additional construction management	1	-	_		5	261.0
	services to March 2002	1				- <del>  `</del>	
		1					
Unbudgeted Contracts	1			i			
	Environmental Health Consultants		,			- 5	50,0 34,0
	Sandis Humber Jones Four Star Cleaning and Restoration	\$ 28,00	<del></del>			-   \$ 5	50,0
	Kim Parker Plantscapes	\$30,00	0	_			
	SILICON VALLEY SECURITY		+	· ·	Milpitas Blvd Landscape		76 6
					(#4140)		75,0
	Provides project site security to completion of the project. Total agmt amount = \$55,038	1	1	1 '	200 Calaveras Blvd Landscap (#4194)	·	
	Andrew Lean settle Building - Addings	ļ	1		000 Telecom (#8093)		
			1		900   Pond (#8141) 900   Parking Circulations (#814		
		_l		3 4,1	000 Parking Circulations (#814		
	Cost Sub-total	s \$ 3,902,61	7	\$ 1,663,	323	\$	3,843,8
					—	\$ (	(323,482
	1		I		 nase orders (including Mauck Sheetme		104,

Totals Project Contingency Punds Remaining = (after Council approval of above change orders)

### **Civic Center Project**

Budget Summary As of January 13, 2003

Total Civic Center Project Budget		38,506,918
Expended and Committed to Date: Expenditures paid to date (through 01/13/03) Contracts and encumbrances approved by Council	36,845,355 <sup>(1)</sup> 1,347,685	
Total Expended and Committed to Date		38,193,040 <sup>(2)</sup>
Uncommitted Budget		313,878
Holds and Unboughts		0 (3)
Remaining Project Contingencies		313,878 (4)

- (1) Represents 95.69% of total Civic Center Project budget
- (2) Represents 99.18% of total Civic Center Project budget
- (3) Represents 0.00% of total Civic Center Project budget
- (4) Represents 0.82% of total Civic Center Project budget

EK 1/15/2003 6:39 PM

### Civic Center Project #8026

### Budget Reconciliation through 01-13-03

No.	ltem .	Adjusted	Total	· · · · · · · · · · · · · · · · · · ·
		Budget	Expended &	Avallable
		11/19/2002	Committed	Budget
1	Design			
	Studios Design & Admin.	2,327,138		
	Geotech Design & Admin.	24,550		
1C1 & C2	Hazmat Design & Monitoring	57,280		
1D	Estimate	8,500		
1E	Other Consultants	83,603		
1F	Printing/Copying/Blueprinting	75,000		
1G	Topo Survey (S-H-J)	16,067		
	Total Design	2,592,138	2,689,818	(97,680)
2	Administration			
2A	City Staff Labor	3,206		
2B	City Staff Support	1,601		
	Total Administration	4,807	4,953	(146)
3	Survey			
3A	Survey	25,000		
38	Title Work (First American)	1,050		l
	Total Survey	26,050	56,049	(29,999)
4	Inspection PM/CM			
4A	Turner	2,075,115		
4B	Special Inspection	250,000		
	Total RM/QM	2,325,115	2条10次80	(32/118)
- 10 P	Renglistrin of AWAY	. 0	0	0
6	Buildings			
6A	Prime Contractors	25,076,330	25,390,656	(314,326)
6B	Misc. Contractors	0	0	0
6C	Change Order Contingency	2,000,000	2,282,675	(282,675)
	Total Buildings	-27,076,330	27,673,331	(597,001)
7	Improvements			
7A	Site Contractors	1,613,000		
78	PG&E	14,866		
	Total Other Improv.	1,627,866	1,121,060	508,806
8	Equipment	4 000 000		
A8	FF&E	1,000,000		
8B	Signage	175,000		
8C	Tel/Data (NEC only)	400 000		
8D	Artwork	100,000		
8E	Audio Visual System	0		
8F	Other	U	TENT OF S	
9	Total Equipment Other	2014(0)UUU	TRANATO:	40,021
9A	Mall Lease (Improvements)	050 000		
9A 9B	Maii Lease (improvements) Tel/Data	950,000		
9C	Move coordination	04.350		
		94,250		
9E	Move Cost to Mall Move Cost to New Bldg.	54,149 150,000	[	
9F	Misc. Costs	75,000		
9G	Previous Costs (Recon Amount)	116,107		
	Total Other		A RTA OTA	(131 765)
9H	Misc. Operating Costs	25,000	0	25,000
9)	Aroject Contingency	2,115,108		645,260
- CONT. 41 (45.5%)	TO THE CONTACT OF INNERTY AND IN THE CONTACT OF THE	NEST THE STATE OF	S THE STATE OF THE	SESSION ALBERTA
	Project Total	AR ADA OHE	38/193/040	212 070
- 10 Car	A STATE OF THE PARTY OF THE PAR	WHALKHALL TAN	SSAMINACIAN AS	26/2% TA MINI

# OTHER CIPS IN CONJUNCTION with the CIVIC CENTER PROJECT SUMMARY OF BUDGET, EXPENDITURES and COMMITMENTS <u>As of January 13, 2003</u>

						AVAILABLE BUDGET
					NEW CONTRACT OR	AFTER NEW CONTRACT
			AMOUNT	TOTAL EXPENSES	NEW CHANGE ORDER	OR NEW CHANGE ORDER
Page #	CIP NO	DESCRIPTION	BUDGETED	& COMMITMENTS	FOR APPROVAL	APPROVED
2	4140	Milpitas Blvd. Landscape	150,000	157,961	-	(7,961)
3	4194	Calaveras Blvd. Median Landscape	150,000	167,359	-	(17,359)
4	8093	Telecommunications Infrastructure	1,150,000	942,980	-	207,020
5	8109	Desktop Technology	371,852	349,298	<b>.</b> .	22,554
6	8141	Pond Renovation	1,650,000	1,649,662	-	338
7	8142	City Hall Technology	1,500,000	1,454,435	-	45,565
8	8143	Parking Circulation Improvements	935,000	935,733	<u> </u>	(733)
TOTAL	. BUDGE	FRELATED TO CITY HALL	5,906,852	5,657,428		249,424